

22/03/2002

PRS

ASS. REC. BY:

REF:

CSA/AXA/17006910/sh3m

Special Instruction:

Surveyor: Sebastian
mermen

ASSIGNMENT (Office)

From (Person):

Khor Saw Theng

of

AXA

Date/Time: 7/4/2017 4:28pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGV 1793P

Insured:

EF 7215K

at Workshop m/s

Kum Chee Motor

Tel:

64563711

of

Blk 12 Gln Ming Ind Est #01-71

Policy No:

GA 669307

Claim No:

COU 28596

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5/4/2017

CA / REV / REP. / REV 24 HRS

1wp

H.O.D. Endorsement:

Date/Time:

7/4/2017 1pm

Person Contacted:

madam4m

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SGV 1793P

EF 7215K

Survey: 10/4/2017; dismantle: 11/4/2017 After repair: 19/4/2017

20/4/2017 @ 2:55pm send email inform saw theng survey without estimate.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS3/AXA17006910/Sh3

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 07-04-2017



Code : AXA2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	EF 7215K	Veh. Inspected	SGV 1793P
Policy No.	GA069307	Coverage (\$)	0.00
Claim No.	C0428596	Excess (\$)	0.00
Assign From	MERIMEN (KHOR SAW THENG)	Assign Date	07/04/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/04/2017	Inspection Date	10/04/2017
Survey held at	KUM CHEW MOTOR WORKSHOP BLOCK 12 SIN MING IND. EST. SECTOR B #01-71 SINGAPORE 575656		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Survey Department Check List

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin: Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	✓			
C Customer Code	✓			
N Assign From	✓			
C Assign Date	✓			
C Veh No (Inspected)	✓			
C Veh No (Insured)	✓			
C D.O.A	✓			
C Policy No	✓			
C Claim No	✓			
C Insurance Authorisation (CA /REV/REP)	✓			
C Report Type (Must Tally with Remarks Description)	✓			
C Weekend Charges	✓			
N Survey held at/Repairer	✓			
C Excess				

Surveyor: Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No	✓			
C Regn Month/Year	✓			
N Vehicle Type	✓			
N Make & Model	✓			
C Engine Capacity. (C.C)	✓			
N Colour	✓			
C Odometer. (Sp.Reading)	✓			
C Chassis No	✓			
N General Condition	✓			
N Steering	✓			
N Brake	✓			
N Modification (Modi)	✓			
C Tyre Size	✓			
N Tyre Make	✓			
C Tyre Balance	✓			
C Date of Inspection	✓			
N Survey held	✓			
N Des.of Damages	✓			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded	✓			
--	---	--	--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition				
C Market Value for OD cases				
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C Days of repair				
C Finalised Amount				
C Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C Resurvey photo Uploaded	✓			
---------------------------	---	--	--	--

Check By:

ahley

22/01/2017

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2017

View Sent Message

This mail is associated with :

***SGV1793P (C0428596)**
[EF7215K]

TP

TEO HOON SENG TIMOTHY

Apr 5 2017 8:00AM

[GOH CHEE HIONG]

Kum Chew Motor Workshop

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **28/04/2017 14:55 PM.**
To AXA_KhorSawTheng
CC AXA_SG
Subject PRS FOR SGV 1793P

Dear Saw Theng,

Please be informed that we have inspected the vehicle **SGV 1793P** on **10.04.2017**.

At the time of inspection, the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Thank you.

Regards,
Ashley

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(New Assignment)

Non-Reporting

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Apr 2017		07 Apr 2017 16:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GOH CHEE HIONG, ID: S0388063Z, Email: KHC@KIMHOCKCHYE.COM								
Main Claimant:	TEO HOON SENG TIMONTHY, ID: S0279090D								
Vehicle Reg. No.:	SGV1793P	Date of Loss:	05/04/2017 08:00 - :59						
Claim Type:	TP / C0428596	Policy/Cover Note No.:	GA069307 (Comprehensive)						
Vehicle Reg. No. (Insured):	EF7215K	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Kum Chew Motor Workshop (HQ) 12 Sin Ming Industrial Estate, #01-71, 575656 Sin Ming - Tel: 6456 3715								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Khor Saw Theng - 6880 4754]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/04/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AXA_SG (07/04/2017): WP / New TP Assignment - C0428596/GA069307 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

7/4/2017 @ 5pm
 mananum
 vehicle in
 survey arrange
 on 14/4/2017

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/04/2017 11:03
Date Of Accident	05/04/2017 08:05
Exact Location Of Accident	JUNCTION OF MARINE PARADE RD AND STILL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGV1793P
Insured/Policyholder	
Name Of Registered Owner	TEO HOON SENG TIMONTHY
NRIC No	S0279090D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97406403
Alternative Phone No	OFFICE-97406403

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P28759805DMA (COMP)
Cover Note Number	

Driver

Name of Driver	TEO HOON SENG TIMONTHY
NRIC No	S0279090D
Date Of Birth	13/11/1939
Occupation	INDOOR
Date Of Driving Pass	12/06/1959
Driving Experience	57 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97406403
Fax Number	
Contact Number	OFFICE-97406403
Email Address	NOEMAIL

Address	BLK 43 MARINE CRESCENT #16-06
Postcode	440043
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	UNKNOWN - REFER TO SKETCH
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	EF7215K
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	GOH CHEE HIONG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

06 APR 2017

06 APR 2017



Signature

6/4/17

Signature


6/4/17

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 9090D

Vehicle Details

Vehicle No.: SGV1793P

Vehicle to be Exported: No

Intended De-registration
Date: 11 Apr 2017

Vehicle Make: TOYOTA

Vehicle Model: VIOS G AUTO

Primary Colour: Blue

Manufacturing Year: 2007

Engine No.: 1NZX566899

Chassis No.: MR053HY9305008849

Maximum Power
Output: 80.0 kW (107 bhp)

Open Market Value: \$14,039.00

Original Registration
Date: 06 Jun 2007

First Registration Date: 06 Jun 2007

Transfer Count: 0

Actual ARF Paid: \$15,443.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 05 Jun 2017

PARF Rebate Amount: \$7,721.00

Intended COE Rebate Details

COE Expiry Date: 05 Jun 2017

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$17,010.00

COE Rebate Amount: \$256.00

Total Rebate Amount: \$7,977.00

The information contained herein is correct as at 11 Apr 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AXA17006910/SH3M2
Date: 02/05/2017**REFERENCE**

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	GA069307
Claimant Vehicle No :	SGV1793P	Insured Vehicle No :	EF7215K
Date of Loss:	05/04/2017	Nature of Claim:	TP
		Claim No:	C0428596

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGV1793P	Engine No:	1NZX566899
Make & Model:	TOYOTA VIOS, 1.5 A (A)	Chassis No:	MR053HY9305008849
Reg. Date:	06/06/2007 (Man. Year: 2007)	Odometer:	65153 km
Colour:	Blue		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	07/04/2017	
Date Inspected:	10/04/2017	Inspected At: Kum Chew Motor Workshop (HQ) 12 Sin Ming Industrial Estate, #01-71 Singapore 575656
Estimated Period of Repair:	0.0 days	

Adjuster: Sebastian Yeang Wai Keen

Manager: Ashley Chong Chin Yan

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 May 2017)
Parts:	143	TOYOTA VIOS 1.5 A (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGV1793P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >