



Your Ref: C0428596

Date: 01st December 2020

Our Ref: CS3/AXA17006910/Qsd3e2-1

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01

AXA Tower

Singapore 068811

(The Motor Claims Department)

Attn : Tan Wancong

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SGV 1793P
INSURED VEHICLE: EF 7215K
ACCIDENT DATE: 05/04/2017**

We thank you for your instruction on 13/10/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGV 1793P from M/s Prestige Appraiser Services.
- b) Final Repair Bill of SGV 1793P from M/s Kum Chew Motor Workshop.
- c) Singapore Accident Statement of Vehicles SGV 1793P and EF 7215K.
- d) Colour damaged vehicle photographs of SGV 1793P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SGV 1793P
Make & Model	: Toyota Vios G Auto
Year of Registration	: 2007
Chassis Number	: MR053HY9305008849
Engine Capacity	: 1497 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.