

ACTUAL - CP/P

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 14.10.2020
Time: 11:18:51
Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305427848
REGN NO : SH 7936L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 02.07.2019
DATE/TIME IN : 14.10.2020 09:15
ACCIDENT DATE : 13.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2534-G	IONIQV2&3 COVER-FR BUMPER	1	418.30	20.00	334.64	X	R
0002 04-01-0104-2418-G	IONIQVC LIP-FR BUMPER	1	35.10	20.00	28.08	/	OR
0003 04-01-0104-0634-G	IONIQVC GRILLE-FRONT BUMP	1	318.80	20.00	255.04	/	OR

SUB-TOTAL : 617.76

JOB NATURE

0000 PB	PANEL BEATING
0001 SP	SPRAYPAINT CHARGE
0002 17-01	CHECK ALL LIGHTING

400.00 390

300.00 100

50.00 30

SUB-TOTAL : 750.00

833.12

TOTAL : 1,367.76

MVA NAME & SIGNATURE
DATE: 14/10/20

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE:

Steve (LKK) wL PM
14/10/20, 3.00pm
P/P
My Bel SM
2 dgs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: