

ASS. REC. BY: Steve 1 REF: CS/SM02021185/1E113

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
CO / IF / WS / IF RES / OO RES / EVA / INV / MY
To inspect Vehicle No: _____
at Workshop m/s: _____
of: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

Ref. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lump Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKT 4510 H Yr Regn: 9/6/15
Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda HRV c.c. 1496
Colour: GJ 92222 A/C: Insured / Std / Nil / N
Sp. Rending: T/Radio: Insured / Std / Nil / N
Eng/No: _____
C/No: MRHR41839FP090134
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modl: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/65R16
R: _____
BS / DUN / EXNOVA / GY (FS) LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal. 4 mm R/Bal. 4 mm
L/Bal. 4 mm L/Bal. 4 mm
D.O.A. 15/10/20 D.O.I. 15/10/20
Survey held at: Ryder
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FRONT AND REAR
The U/C / Chassis frame / Body Structure affected due to collision

| Date / Time | Action / Instruction |
|-------------|---|
| | MV - 57K |
| | PV - 43,500 |
| | NV - 13,500 |
| | LUMP SUM \$8750, 7 DAYS (RED: 9261.28; 51%) |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | 18011.28 |

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report
Date/Time, File Return to?

Days Of Repair: 7
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)
Survey Fee: _____
Transportation: _____
S + RS: _____
Photos: _____
Others: _____
TOTAL: _____

Pop. Format: _____
Lump Sum / L.B.I. : _____

Ryder

Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SKT4510H

Model: HONDA HRV 1.5 LX CVT

(9/6/2015)

Accident Date : 15/10/20

Location : PIE TOWARDS TUAS BEFORE CLEMENTI EXIT

3P: SLD8654Y (SOMPO)

| S/Nos. | Qty | Description | List \$ | S/Nett \$ | Nett \$ |
|--------|--------|---|----------|-----------|---------|
| 1 | 1 pc | Front bumper / DD | 598.00 | - | - |
| 2 | 1 pc | Front bumper enforcement / DT | 365.20 | - | - |
| 3 | 10 pcs | Front bumper clips / MC | - | 50.00 | - |
| 4 | 1 pc | Front bumper n/s retainer / BR | 79.00 | - | - |
| 5 | 1 pc | Front bumper n/s fog lamp ? | 309.30 | - | - |
| 6 | 1 pc | Front bumper n/s fog lamp garnish cover / CUT | 52.30 | - | - |
| 7 | 1 pc | Front bumper n/s fog lamp bracket / BR | 60.00 | - | - |
| 8 | 1 pc | Front grille (Upper) / BR | 256.10 | - | - |
| 9 | 1 pc | Front grille chrome (Upper) / CUT | 167.20 | - | - |
| 10 | 1 pc | Front grille emblem (Upper) / MC | 80.00 | - | - |
| 11 | 8 pcs | Front grille clips (Upper) / MC | - | 40.00 | 19 |
| 12 | 1 pc | Front grill middle / BR | 357.50 | - | - |
| 13 | 8 pcs | Front grill middle clips / MC | - | 40.00 | 19 |
| 14 | 1 pc | Front bumper lower grille / CUT | 107.90 | - | - |
| 15 | 1 pc | Front bumper (lower) stone guard X | 356.00 | - | - |
| 16 | 1 pc | Front n/s head-lamp / BR | 638.30 | - | - |
| 17 | 1 pc | Front n/s fender X R | 726.30 | - | - |
| 18 | 1 pc | Front n/s fender wheel guard ? | 114.00 | - | - |
| 19 | 8 pcs | Front n/s fender wheel guard clips ? | - | 40.00 | - |
| 20 | 1 pc | Front n/s fender wheel arch garnish ? | 110.00 | - | - |
| 21 | 1 pc | Front regn. no. plate / BR DT | - | - | - |
| 22 | 1 pc | Front regn. no. plate bracket / BR | - | - | - |
| 23 | 1 pc | Rear bumper / BR | 998.10 | - | - |
| 24 | 10 pcs | Rear bumper clips / MC | - | 30.00 | - |
| 25 | 1 pc | Rear bumper n/s retainer / BR | - | - | - |
| 26 | 1 pc | Rear bumper n/s reflector / BR | 171.25 | - | - |
| 27 | 1 pcs | Rear bumper n/s garnish / BR | 171.25 | - | - |
| 28 | 1 pc | Rear n/s wheel arch / BR | 134.50 | - | - |
| 29 | 1 pc | Rear n/s tail-lamp / CUT | 627.10 | - | - |
| 30 | 1 pc | Rear tail-gate / DT | 1,297.00 | - | - |
| 31 | 1 pc | Rear tail-gate weatherstrip / TN | 365.00 | - | - |
| 32 | 1 pc | Rear tail-gate emblem X MC | 105.00 | - | - |
| 33 | 1 pc | Rear tail-gate 'HRV' emblem / MC | 85.00 | - | - |

| | | | | | |
|-----------------|--------|---|-----------|-----------|------|
| 34 | 1 pc | Rear tail-gate 'i-VTEC' emblem | 95.00 | - | - |
| 35 | 1 pc | Rear tail-gate 'H' logo | 74.00 | - | - |
| 36 | 1 pc | Rear tail-gate inner trim | 143.90 | - | - |
| 37 | 12 pcs | Rear tail-gate inner trim clips | - | 60.00 | - |
| 38 | 1 pc | Rear tail-gate n/s reflector | 360.00 | - | - |
| 40 | 1 pc | Rear end panel | 420.00 | - | - |
| 41 | 1 pc | Rear end panel panel inner trim | 145.60 | - | - |
| 42 | 6 pcs | Rear end panel panel inner trim clips | - | 30.00 | - |
| 43 | 1 pc | Rear windscreen moulding | 234.5 | - | - |
| 44 | 1 pc | Rear windscreen sealant | - | 80.00 | 49 |
| 45 | 1 pc | Rear n/s fender inner garnish | 188.9 | - | - |
| 46 | 1 pc | Rear n/s fender | 1324 | - | - |
| 47 | 1 pc | Rear buzzer assembly | 210.00 | - | - |
| 48 | 1 set | Rear reverse sensor | - | 280.00 | 207 |
| Sub-Total | | | 11,587.20 | 650.00 | 0.00 |
| 20% | | | - | 0% | 0% |
| After Less %: | | | 9,269.76 | 650.00 | 0.00 |
| Labour | | | | | |
| 1 | | To remove & replace front & rear damage parts | 1700 | 1,800.00 | 1100 |
| 2 | | To spray painting | 1100 | 1,600.00 | 1000 |
| 3 | | To remove and refit rear windscreen. | | 120.00 | 1 |
| 4 | | To remove and replace rear tail-gate. | | 100.00 | 50 |
| 5 | | To check wiring. | | 80.00 | 30 |
| Sub-Total: | | | | 3,700.00 | |
| Total: | | | | 13,619.76 | |
| After Less 20%: | | | | 10,895.81 | |

Chan

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)



bizSAFE AL 8778 1999
S T R 24 hr accident call

Mobil 1



Steve (LKK)

WL M

15/10/99, 3-30pm

7 days

L/S

By AL sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|------------------------------------|
| Date Of Report | 15/10/2020 11:18 |
| Date Of Accident | 15/10/2020 07:20 |
| Exact Location Of Accident | PIE TWDS TUAS BEFORE CLEMENTI EXIT |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|--|---------------------------------------|
| Vehicle Registration Number | SKT4510H |
| Insured/Policyholder | |
| Name Of Registered Owner | LAU TZE HON |
| NRIC No | SXXXX041Z |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-97810849 |
| Alternative Phone No | OFFICE-97810849 |
| Vehicle Particulars | |
| Manufacturer | HONDA |
| Model | HRV 1.5 LX CVT |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| Insurance Company | |
| Name of Insurance Company | INDIA INTERNATIONAL INSURANCE PTE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | D19MPC0002550_01 |
| Cover Note Number | |
| Driver | |
| Name of Driver | JEANNIE WONGSODIHARDJO |
| NRIC No | SXXXX429I |
| Date Of Birth | 02/08/1975 |
| Occupation | INDOOR |
| Date Of Driving Pass | 27/12/1999 |
| Driving Experience | 20 YEARS AND 9 MONTHS |
| Gender | FEMALE |
| Mobile Number | (LOCAL) +65-97810849 |
| Fax Number | |
| Contact Number | OFFICE-97810849 |
| Email Address | NOEMAIL |

Address BLK 57 HILLVIEW AVENUE
#04-02
Postcode 669568
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured CHILDREN
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 3
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1:

Vehicle Registration Number SLD8654Y
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2:

Vehicle Registration Number SKL2098L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

JEANNIE WONGSODIHARDJO

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

SKT4510H

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO


Address

Postcode

Accident Sketch Plan

SKETCH PLAN:

PIE TWDS TUAS BEFORE CLEMENTI EXIT




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG PIE TWDS TUAS BEFORE CLEMENTI EXIT. VEHICLE AHEAD SLOWED DOWN AND STOPPED. I FOLLOWED SUIT. MOMENTS LATER WHILE MY VEHICLE WAS STILL STATIONARY, VEHICLE B REAR-ENDED MY VEHICLE. THE IMPACT FORCED MY VEHICLE FORWARD TO HIT VEHICLE C.

DECLARATION

I/ We declare the foregoing particulars are true in every respect.

* 
 Policyholder's Signature
 Date & Time:

* 
 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC / FIN No.: