



## Performance Motors Limited

Sime Darby Motors Company  
Co. Reg. No. 157451556M GST Reg. No M2-0020081-X  
Toll-Free Number: (1800-2255259)

307, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 56291  
Date Estimated : 15/10/2020  
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 7

## - ESTIMATE REPAIR FOR -

Poh Eng Hong  
67 Poh Huat Road  
#02-01

Singapore 546776

## - ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK9880E	WBAJG120005N06611	30/04/2019	X1 sDrive18i	0

## DESCRIPTION

To replace rear bumper, tailgate, tail panel outer,  
tail panel inner, crossmember, trunk floor left, rear left  
fender, repair rear left chassis including knocking and  
straighten dent area.

10200 VALUE  
12,750.00

To painting rear bumper, tailgate, tail panel, trunk  
floor, rear left fender, spoiler and roof frame.

4820 VALUE  
5,356.00

To tow accident vehicle to PML workshop.

✓ 195.00

To supply rear emboss number plate.

X 83.00

To remove and install rear hat -tray, rear seat, carpet and r  
oof top lining to facilitate r epair.

742 VALUE  
873.00

To remove and install boot com partment carpet and garnish to  
facilitate repair.

230 VALUE  
271.00

To replace rear windscreen gla ss.

✓ 676.00

To conduct water leak tests.

✓ 75.00

To supply and install rear windscreen solar film.

photo ✓ 531.00

To mount accident vehicle on c elette bench or Car-O-liner to  
facilitate re-alignment of bo dy / chassis accordance with B  
MW specification.

photo 2507? 2,950.00

To conduct chassis alignment m easuring check using Car-O-Lin  
er measuring system accordance with BMW specification.

Report - ? 531.00

To replace bootlid smart opene r control unit, top and bottom  
sensor line including progra m and conduct check for proper  
function.

564? 661.00

To check electrical wiring sys tem and lighting at the rear s

150  
177.00

**Performance Motors Limited**

A Sime Darby Motors Company

Co. Reg. No. 197401559K GST Reg. No M2-0020081-X

Toll-Free Number (1800-2255269)

313, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64796624280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**

Estimate No. : b1 56291  
 Date Estimated : 15/10/2020  
 Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK9880E	WBAJG120005N06611	30/04/2019	X1 sDrive18i	0

**DESCRIPTION****VALUE**

ection for proper function.

To transfer lock mechanism from old to new bootlid including  
 conduct check on new bootlid central locking system for pro  
 per function.

450. 531.00

To remove old PDC assembly, re place damaged parts and reconn  
 ect to new bumper including re connet to new bumper and condu  
 ct check for proper function.

150. 177.00

To replace rear exhaust silenc er including alignment system  
 and conduct check for leak.

photo 450 531.00

To replace front exhaust silen cer including alignment system  
 and conduct check for leak.

photo? 450 531.00

To replace exhaust catalytic converter including conduct  
 check for leak.

photo 952? 1,121.00

To carry out body cavitypreser vation. (Per panel).

100 118.00

To carry out body cavitypreser vation. (For cut panel).

451 531.00

Sundries

✓ 150.00

To vaccum glass debris.

✓ 226.00

To check steering geometry and conduct wheel alignment in ac  
 cordance with BMW specificatio ns. (1x).

Report 451? 531.00

Total Labour 1: **29,576.00**

**DESCRIPTION****QTY****PRIC****VALUE**

PLASTIC NUT FOR COARSE THREADED PIN

12

0.85

Nil ✓ 10.20

BLIND RIVET NUT WITH COLLAR M5

1

5.55

Nil ✓ 5.55

COLLAR SCREW

1

3.65

Nil ✓ 3.65

SILENCER CLAMPING BUSH

1

54.60

Nil ✓ 54.60

GASKET RING

1

30.45

Nil ✓ 30.45

V BAND CLAMP

1

43.05

Nil ✓ 43.05

RUBBER MOUNTING

2

17.70

Nil ✓ 35.40

FRONT SILENCER

1

1,020.75

? 1,020.75

MUFFLER CLAMP D=65.2MM

1

42.00

? 42.00

REAR SILENCER

1

1,178.35

bt ✓ 1,178.35

TAILPIPE TRIM BLACK CHROME

1

112.20

cut ✓ 112.20

HOLDER EXHAUST SYSTEM

1

58.65

bt ✓ 58.65

EXCH CATALYTIC COVERTER CLOSE TO EN

1

2,118.50

? 2,118.50

Cross member

1

537.25

? 537.25

# PERFORMANCE MOTORS LIMITED

A Sime Darby Motors Company  
Co. Reg. No. 19401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

301, Alexandra Road  
Sime Darby Performance Centre  
Singapore 119941  
Fax: 64797770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 56291  
Date Estimated : 15/10/2020  
Prepared By : Inthiran A/L Thurasamy

Page No. : 3 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK9880E	WBAJG120005N06611	30/04/2019	X1 sDrive18i	0

DESCRIPTION	QTY	PRIC	VALUE
INTERIOR TAIL TRIM	1	317.25	? 317.25
TAIL PANEL	1	403.75	bt 403.75
Cross member support	1	152.05	? 152.05
RR LH FENDER	1	1,725.45	bt 1,725.45
LH TRUNK FLOOR	1	112.10	bt 112.10
Positionieru	1	5.80	nei 5.80
REINFORCEMENT PLATE UNIVERSAL	1	52.50	nei 52.50
LH REINFORCEMENT PLATE SILL	1	53.75	nei 53.75
LH REINFORCEMENT PLATE C PILLAR	1	53.75	nei 53.75
LH REINFORCEMENT PLATE D PILLAR	1	65.35	nei 65.35
T WELD BOLT L=5.4MM	12	0.90	nei 10.80
WASHER GASKET	2	11.20	nei 22.40
REAR LH BUMPER MOUNT	1	161.40	nei 161.40
RR BUMPER CARRIER	1	496.35	? 496.35
REAR BUMPER TRIM PANEL BOTTOM (BASI	1	206.85	nei 206.85
MOUNTING SMART OPENER	1	45.55	? 45.55
RR BUMPER LH CORNER MOUNTING	1	142.65	? 142.65
RR BUMPER LH CORNER MOUNTING	1	142.65	? 142.65
REAR BUMPER PANEL PRIMED	1	903.40	dei 903.40
REAR BUMPER MIDDLE TRIM PANEL (PDC)	1	265.65	dei 265.65
EMBLEM GROMMET	2	0.85	nei 1.70
BMW PLAQUE WITH ADHESIVE FILM	1	71.60	nei 71.60
LETTERING S DRIVE 18i	1	96.65	nei 96.65
LETTERING X1	1	64.45	nei 64.45
PLASTIC NUT	6	0.85	nei 5.10
STRIKER BOOT LID	1	59.80	? 59.80
LOCK TRUNK LID	1	229.10	? 229.10
BUMP STOP	10	3.75	nei 37.50
REAR WINDOW (ESG)	1	851.00	nei 851.00
REAR LH SIDE WINDOW FIXED (ALU)	1	319.45	nei 319.45
ODDMENTS TRAY	1	45.95	? 45.95
TRUNK TRIM LH	1	225.35	? 225.35
REAR BUMPER HEAT INSULATION	1	69.85	bt 69.85
LOWER TAIL LID TRIM PANEL (SCHWARZ)	1	164.65	? 164.65
LH TRUNK LID PANEL TRIM (EVERESTGRA	1	31.50	? 31.50
LH TRUNK LID PANEL TRIM (EVERESTGRA	1	31.50	? 31.50
RH TRUNK LID PANEL TRIM (EVERESTGRA	1	31.50	? 31.50
REAR LH WHEEL HOUSING COVER	1	143.25	? 143.25
Undershield	1	80.60	? 80.60
BOOTLID SEALING	1	166.50	? 166.50
REAR LH WHEEL ARCH TRIM	1	151.80	dei 151.80
PLUG BLACK D=5MM	7	0.95	? 6.65
SENSOR WIRE FOR SMART OPENER TOP	1	46.30	? 46.30
SENSOR WIRE FOR SMART OPENER BOTTOM	1	50.90	? 50.90
CONTROL UNIT SMART OPENER	1	497.05	? 497.05
REAR LH REFLECTOR	1	38.85	nei 38.85
WIPER ARM PASSENGER'S SIDE	1	92.60	? 92.60
REAR WIPER BLADE	1	43.00	? 43.00
REAR WINDOW WIPER ARM	1	74.10	? 74.10

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159541  
Fax: 64747779

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 56291  
Date Estimated : 15/10/2020  
Prepared By : Inthiran A/L Thurasamy

Page No. : 4 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK9880E	WBAJG120005N06611	30/04/2019	X1 sDrive18i	0

DESCRIPTION	QTY	PRIC	VALUE
WIPER ARM COVER	1	11.55	11.55
REAR RH LIGHT IN TRUNK LID	1	277.10	277.10
REAR LH WATER GUTTER COVER	1	29.70	29.70
REAR LH LIGHT IN THE SIDE PANEL	1	397.85	397.85
ULTRASONIC SENSOR BLACK	2	249.95	499.90
DECOUPLING RING PDC TORQUE CONVERTER	4	5.10	20.40
BMW ADVANCED CAR EYE 2.0 (BASIS)	1	837.20	837.20
CAVITY PROTECTION WAX REMOVER 500ML	1	18.45	18.45
BLIND RIVET AVIBVLB	12	0.55	6.60
BLIND RIVET AVIBVLB	25	0.55	13.75
SCREW (SF PLUS M5X15)	4	0.55	2.20
SCREW (SF PLUS M5X15)	2	0.55	1.10
(DG/SL) BODY ADHESIVE K5B (195ML)	1	331.80	331.80
(DG) BODYWORK ADHESIVE K5A (50ML)	1	114.45	114.45
(DG) BODYWORK ADHESIVE K5A (50ML)	1	114.45	114.45
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
PUNCH RIVET N4	60	0.55	33.00
(DG/SL)ADHESIVE PRIMER VP 206 (30ML)	1	27.85	27.85
(S/L) SEAM SEAL 300ML	1	33.80	33.80
(S/L) SEAM SEAL 300ML	1	33.80	33.80

Total Parts : 17,464.80

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No.	Claim No.
Date&Time 16/10/20 01:50	Excess \$
Surveyor's Name Tanjir	Sign
Surveyor's Tel 97495749	Authorised Yes / No
Authorised Date 16/10/20	Time
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's E-mail tanjir@thurasamy.com	
No. of Working Days Recommend 22 days	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	29,576.00
Parts	:	17,464.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	3,292.86
Grand Total	:	50,333.66

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTES

1. Please report the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT:

Date Of Report 14/10/2020 08:54  
Date Of Accident 14/10/2020 06:45  
Exact Location Of Accident ALONG SENGKANG EAST ROAD  
Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SMK9880E  
**Insured/Policyholder**  
Name Of Registered Owner POH ENG HONG  
NRIC No SXXXX184E  
Email Address LEKKB@HOTMAIL.COM  
Mobile Phone No (LOCAL) +65-98360595  
Alternative Phone No OTHERS-98360595  
**Vehicle Particulars**  
Manufacturer BMW  
Model X1 SDRIVE18I-1.5 LED NAV (A)  
Exact Purpose for which vehicle was being used at time of accident  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number 29133143 APO  
Cover Note Number

### Driver

Name of Driver POH ENG HONG  
NRIC No SXXXX184E  
Date Of Birth 23/05/1972  
Occupation INDOOR  
Date Of Driving Pass 23/03/2000  
Driving Experience 20 YEARS AND 6 MONTHS  
Gender FEMALE  
Mobile Number (LOCAL) +65-98360595  
Fax Number  
Contact Number OTHERS-98360595  
Email Address LEKKB@HOTMAIL.COM

Address 67 POH HUAT ROAD #02-01  
 Postcode 546776  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 Vehicle -  
 Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name SENGKANG NEIGHBOURHOOD POLICE CENTRE  
 Police Station Address ROAD: 2 SENGKANG SQUARE #01-02 SINGAPORE , POSTCODE: 545025 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800 - 3438999 - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

ON 14/10/2020 AT 6:44AM, I WAS TRAVELLING ALONG SENGKANG EAST ROAD AND SENGKANG EAST WAY JUNCTION. I SLOWED DOWN WHEN I SAW THE TRAFFIC LIGHT TURNED AMBER. SUDDENLY I FELT AN IMPACT AT THE REAR. MY WINDSCREEN SHATTERED UPON THE IMPACT AND MY CAR SURGED FORWARD. I ALIGHTED FROM MY CAR TO CHECK. I REALIZED THAT VEHICLE B HAD COLLIDED INTO MY CAR, CAUSING DAMAGES AT THE REAR. I FELT UNWELL AFTER THE ACCIDENT. \*\* REFER TO POLICE REPORT NO. T/20201014/2040 \*\*

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: SD CARD WITH OWNER  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number GBG4393D  
 Vehicle Make/Model/Colour TOYOTA / DYNA  
 Details Of Properties VEH B  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver KOH YAM KOON  
 NRIC/Passport Number SXXXX086B  
 Contact Number 83326106

Address

Postcode

Insurance Company Name

Nature Of Damage

FRONT PORTION

No. Of Passenger (Including Driver)

1

**DETAILS OF INJURED PERSON 1:**

Name

POH ENG HONG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SMK9880E

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

(DRIVER)

Postcode



## SKETCH PLAN


## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14/10 @ 6:44 am, I was travelling along Senyang East Rd & Senyang East Way junction. I slowed down ~~after~~ when I saw the traffic light turned amber. Suddenly I <sup>felt</sup> an impact at the rear. My underscreen shattered upon the impact and my car surged forward. I alighted from my car to check. I realized that car B had collided into my car, causing damages at the rear. I felt unusual after the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

GRAB/ACC Incident Form\_V3

## ► BMW X1 sDrive18i

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

# VANTAGE PRE-OWNED

<b>Price</b>	<b>\$129,800</b>		
<b>Depreciation</b> ⓘ	\$12,630 /yr View models with similar depre	<b>Reg Date</b>	30-May-2019 (8yrs 7mths 10days COE left)
<b>Mileage</b>	31,995 km (23k /yr)	<b>Manufactured</b> ⓘ	2019
<b>Road Tax</b> ⓘ	\$684 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b> ⓘ	\$69,716 as of today (change)	<b>OMV</b> ⓘ	\$35,730
<b>COE</b> ⓘ	\$52,502	<b>ARF</b> ⓘ	\$42,022
<b>Engine Cap</b>	1,499 cc	<b>Power</b>	103.0 kW (138 bhp)
<b>Curb Weight</b> ⓘ	1,430 kg	<b>No. of Owners</b> ⓘ	2
<b>Type of Vehicle</b>	SUV		

### Features

BMW TwinPower Turbo 3 Cylinder Engine With 138Bhp, 220Nm Of Torque. 0-100Km/H In 9.7s, Top Speed 200Km/H, 7 Speed Transmission DCT, Front Wheel Drive. View specs of the BMW X1

### Accessories

iDrive With GPS, Bluetooth, Contactless Boot Release, Front And Back Sensors, Adjustable Rear Seats, Keyless Entry, Multi-function Steering Wheel.

### Description

Agent Unit. Low Mileage. Own With A Peace Of Mind From Vantage Pre-Owned, A Member Of The Sime Darby Group. Complete With Our Comprehensive 72 Points Mechanical And Safety Inspection, Finance And Trade-In Welcomed. Call For An Exclusive Appointment To View And Test Drive Today.

### Category

PARF Car

### Status

Available

### Resources



#### Car Valuation - Free

Find out the market value of your existing car for free. Get started



#### Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more




#### sgCarMart Used Car Warranty

Get our warranty for \$0 future car repair bills. Learn more




### Price Chart

### Summary



Click on the point to view the vehicle




Shortlist



Compare



Report Error



More Actions

### Seller Information

#### Vantage Pre-Owned

20 vehicles for sale. 77 sold in past 3 mths

305 Alexandra Road #02-01  
Vantage Automotive Centre  
Tel: 63762277  
Search cars nearby

Ronnie Ching  
Louis Chan

85887833  
96965133

## VANTAGE PRE-OWNED



A Sime Darby Motors Company

Posted on: 17-Oct-2020 | Last Updated on: 17-Oct-2020

### Upfront Payment

► more Financial info

<b>Transfer Fee</b> ⓘ	\$25	
<b>Down Payment</b> ⓘ	\$51,920 (change)	Maximum 60% Loan
<b>1st Instalment</b> ⓘ	\$1,121	Based on 2.98% interest rate
<b>Total Upfront Payment</b> ⓘ	\$53,066 (excluding insurance)	Check with seller for exact figure

### Products and Services

► View All

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	184E
Vehicle Details	
Vehicle No.:	SMK9880E
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Oct 2020
Vehicle Make:	B.M.W.
Vehicle Model:	X1 SDRIVE18i LED NAV
Primary Colour:	Black
Manufacturing Year:	2019
Engine No.:	33995617B38B15A
Chassis No.:	WBAJG120005N06611
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$35,142.00
Original Registration Date:	30 Apr 2019
First Registration Date:	30 Apr 2019
Transfer Count:	1
Actual ARF Paid:	\$41,199.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2029
PARF Rebate Amount:	\$30,899.00
Intended COE Rebate Details	
COE Expiry Date:	29 Apr 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,209.00
COE Rebate Amount:	\$36,756.00
Total Rebate Amount:	\$67,655.00

The information contained herein is correct as at 19 Oct 2020