

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/11120011211/ubs3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.


Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA



Front

R/Bal. mm

L/Bal. mm

D.O.A. 10/10/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S, O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. mm

L/Bal. mm

D.O.I. 16/10/20

Date / Time

Action / Instruction

23/11/2013 12:00 confirmed with MR TEO

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) ___ S + RS, ___ SI

) Photos

) Others

TOTAL

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

INDIA

Mr. Jasper

Name : Victor Rajesh Naidu

Accident Date : 10-Oct-20

Vehicle No : FBL797Y

Vehicle Model : Kymco
Downtown
2001

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fork assy	1,300.00 X
1	Front fender	220.00 X
1	Front centre lower cover	180.00 ✓
1	Rear side fairing R/H	260.00 X
1	Front fairing	280.00 ✓
1	Centre side cover - R/H	160.00 ✓
1	Brake lever - R/H	65.00 ✓
1	Balancer - R/H	50.00 ✓
1	Mirror - R/H	160.00 X
1	Handle-bar	170.00 X
1	Exhaust pipe assy	985.00 X
1	Exhaust cover	170.00 ✓
1	Exhaust end cover	120.00 ✓
		\$ 4,120.00
		Less 10%
		\$ 412.00
		\$ 3,708.00
	<u>Special Nett Items</u>	
1	Bearing cone (1 set)	120.00 X
		\$ 120.00

S/No.	Labour	
1	To provide towing	\$ 80.00 X
2	To check wiring and reset headlamp focusing	\$ 80.00 X
3	To respray painting	\$ 600.00
4	To provide labour	\$ 480.00
		\$ 1,240.00
		\$ 5,068.00

Singapore Dollars: Five Thousand and Sixty-Eight only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

EROFIA MOTOR TRADING PTE LTD