

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM20011223/Aes3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	14/09/2021	
	ATTN:VALE OH			Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SME 6595E	Veh. Inspected	ł	SML 3586P	
	Policy No.	VA1 / GA404722	Coverage (\$)		0.00	
	Claim No.	S0M02VFO	Excess (\$)		0.00	
	Assign From		Assign Date		16/10/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI AVANTE	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	KMHD841CMKU891134	Colour		GREY	
	Odometer	33725 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	KUMHO		6 mm	
	L/H Front Tyre	205/55 R16	KUMHO		6 mm	
	R/H Rear Tyre	205/55 R16	KUMHO		6 mm	
	L/H Rear Tyre	205/55 R16	KUMHO		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	12/10/2020	Inspection Dat	e	16/10/2020	
	Survey held at	CAS GARAGE PTE LTD	•			
		NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
	<del>- '</del>					