



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2007481
INV Date 09/11/2020
Reference CS/EQI20011239/Uqf3e2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SMQ 9702E
Insured Veh. SKT 3207R
Claim No. DM20HO01516-JG
Policy No. DMPPHQ20-003330
Accident Date 14/10/2020
Inspection Date 20/10/2020

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CS/EQI20011239/Uqf3e2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 09-11-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKT 3207R	Veh. Inspected	SMQ 9702E
Policy No.	DMPPHQ20-003330	Coverage (\$)	0.00
Claim No.	DM20HO01516-JG	Excess (\$)	0.00
Assign From	JOEL GOH	Assign Date	16/10/2020

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KNAF3416MK5047524	Colour	BLACK
Odometer	10767	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	NEXEN	8 mm
L/H Front Tyre	205/55 R16	NEXEN	8 mm
R/H Rear Tyre	205/55 R16	NEXEN	8 mm
L/H Rear Tyre	205/55 R16	NEXEN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/10/2020	Inspection Date	20/10/2020
Survey held at	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 9702E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RH LAMP ASSY-HEAD (SN)	NOT NECESSARY	1,219.00	-
1	COVER-FRONT BUMPER (SN)	DEEP CUT	633.00	633.00
1	LWR GRILLE-FRONT B (SN)	SCRATCHED	262.00	262.00
10	FASTENER-BUMPER (SN)	NECESSARY	20.00	20.00
1	RH BRACKET-FR BUMPER (SN)	NOT NECESSARY	22.00	-
1	LH BRACKET-FR BUMPER (SN)	NOT NECESSARY	22.00	-
1	RH MOULDING-FRONT BU (SN)	SCRATCHED	36.00	36.00
1	RH LAMP ASSY-SIDE (SN)	SCRATCHED	143.00	143.00
1	RH AIR DUCT-FR BUMPE (SN)	NOT NECESSARY	15.00	-
1	ORNAMENT-KIA NO.1 (ADDITIONAL)(SN)	NECESSARY	32.00	32.00
			2,404.00	1,126.00
<u>LABOUR</u>				
	DIAGNOSTIC-SCANNING.		250.00	250.00
	TO CHECK ALL LIGHTING/WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS.		100.00	80.00
	TO REPLACE RH HEADLAMP,FRONT BUMPER UPR & LWR,SIGNAL LIGHT,CLIPS,BRACKETS,ETC. STRAIGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS.		1,200.00	600.00
	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS.		1,260.00	420.00
			2,810.00	1,350.00
GRAND TOTAL			5,214.00	2,476.00
RECOMMENDED COST OF REPAIRS				2,476.00

Report Ref No. CS/EQI20011239/Uqf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110	Cust No/Name LCV11683/Mr Ong Han Lee(Wang Hanli)
Contact No	Reg No/Reg Date SMQ9702E*ECB19 / 12/12/2019
	Date In/Mileage 02/11/2020/ 11445
	Chassis No KNAF3416MK5047524
	Engine No G4FGKH741988
	Make/Model KIA/CER1.6AEXG333
	Colour/Trim ABP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
F0000061	Credit	02/11/2020/ 11:33	DS	303 / Renemer	54931	
Description of Goods / Services						
X	KS 86318 3R 500	ORNAMENT - KIA NO. 1	Qty	Unit Price	Disc%	Amount
Z	NOTES	ADD	1.00	32.00	0.00	32.00
SUPPLEMENTARY ITEM						
Estimate						
Confirm & accepted by			Parts 32.00			
			Labour 0.00			
			Standard Menu 0.00			
			Specialist Job 0.00			
			Others(Lub,etc) 0.00			
			Sundry 0.00			
Authorized signatory and company stamp			Total(w/o GST) 32.00			

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/10/2020 15:21
Date Of Accident	14/10/2020 09:00
Exact Location Of Accident	WOODLANDS SPORTS COMPLEX, OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMQ9702E
Insured/Policyholder	
Name Of Registered Owner	ONG HAN LEE
NRIC No	S7827147G
Email Address	DARRENOHL78@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96903258
Alternative Phone No	OTHERS-96903258

Vehicle Particulars

Manufacturer	KIA
Model	CERATO-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	STATIONARY MODE,PARKED IN A LOT
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	190025928
Cover Note Number	

Driver

Name of Driver	ONG HAN LEE
NRIC No	S7827147G
Date Of Birth	20/09/1978
Occupation	OUTDOOR
Date Of Driving Pass	19/09/2000
Driving Experience	20 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96903258
Fax Number	
Contact Number	OTHERS-96903258
Email Address	DARRENOHL78@GMAIL.COM

Address	BLK 996B BUANGKOK CRESCENT #16-901
Postcode	532996
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT3207R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MRS GOH
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 15/10/20
e 1230h

Driver's Signature


(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14/10/20 @ around 0900hrs, I parked my vehicle at a parking lot, open carpark of Woodlands Sport Complex. At around 1230hrs when I went to retrieve my vehicle, I saw a note stating 'I may have scratched your car 98210303'. I then noticed that my front right bumper sustained scratch marks. I called the number on the note and spoke to one Mr Goh who mentioned that his wife had drove # vehicle 'SLT 3207 R' and had hit my car while reversing.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 15/10/20 @ 1440hrs

©MARRAC SketchPlanForm V3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMQ 9702E

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMQ 9702E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMQ 9702E

RE-INSPECTION

