



Your Ref: 7261450977SG003

Date: 25th November 2020

Our Ref: CS1/AIG20011266/Uqf3e2

M/s AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #09-16

Aig Building

Singapore 079120

(The Motor Claims Department)

Attn : Cheok Lee Wai

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBF 7912S
INSURED VEHICLE: SLK 5586T
ACCIDENT DATE: 28/08/2018**

We thank you for your instruction on 16/10/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBF 7912S from M/s Sincere Appraisal Services Pte Ltd.
- b) Singapore Accident Statement of Vehicle GBF 7912S, SLK 5586T and GBE 7883Y.
- c) Colour damaged vehicle photographs of GBF 7912S.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GBF 7912S
Make & Model	: Nissan NV200
Year of Registration	: 2017
Chassis Number	: VM20100365
Engine Capacity	: 1597 cc

2. We recommend that the repairs of the entire damage require about 15 (Fifteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.