

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA4535Y
MAKE : HYUNDAI
MODEL : i40

DATE: 17. Oct. 2020
MVA: LOKE WY
DOA: 17. Oct. 2020

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper X R			\$1,106.00
10	Rear Bumper Clips X N/A		\$2.20	\$22.00
1	Rear Bumper Side Bracket - RH X N/A			\$35.60
1	Rear Bumper Reflector - RH X N/A			\$32.00
1	Rear Door RH X R			\$2,201.10
1	Rear Door Handle RH X N/A			\$36.30
1	Rear Fender RH X N/A			\$2,171.40
1	Rocker Panel Garnish RH X N/A			\$682.80
1	Rear Wheel Hub Cap X N/A			\$107.10
SUB TOTAL				\$6,394.30
LESS 20%				\$1,278.86
DISCOUNTED TOTAL				\$5,115.44
1	Rear Door Advertisement Sticker RH / MK			\$100.00
1	Rear Bumper Advertisement Sticker / MK			\$100.00
1	Rear Bumper Rubber Mat X			\$50.00
1	Rear Door ComfortDelgro Apps Sticker / MK			\$80.00
				\$330.00
Labour Charge				
1	Panel Beating		280	\$1,000.00
1	Spray Painting Charge		800	\$1,000.00
1	Wiring Charge		30	\$60.00
1	Remove/refix Reverse Sensor		X	\$120.00
1	Door Transfer		X	\$120.00
TOTAL LABOUR				\$2,300.00
ESTIMATE TOTAL				\$7,745.44

Nett
Nett
Nett
Nett

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Steve (CLKK) ML ML
19/10/20, 11.00a
2 dys
L/S
My AL SLy

ORIDELGRO ENGINEERING

Member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

206 Braddell Road Singapore 579701

Mainline : 65 6383 6280 Facsimile : 65 6280 9755

Workshops

69 Luyang Drive Singapore 508980

381 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 11009700

320 Pandan Road Singapore 1100640

24 Serangoon Loop Singapore 758156

7 Sengkang Kallang Way Singapore 728191

501 Yishun Industrial Park A Singapore 76873

Date/Time: 17.10.2020 10:50

Page : 1

Am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4037133

JC NO.: 305428493

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

REGN NO: SHA4535Y

MILEAGE

MAKE: HYUNDAI

FUEL

MODEL I-40

DATE/TIME IN 17.10.2020 08:45

YR OF MANU 28.03.2015

TARGET DATE

CHASSIS CODE KMILB41UMFU065930

COMPLETION DATE/TIME:


COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 17.10.2020
NATURE: 3P 17.10.2020

S/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHA4535Y

YY

Vehicle No.: SHA4535Y

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard