



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20011286/Avf3q2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRESINGAPORE  
239924

Date : 03-11-2020



Code : AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMH 220K	Veh. Inspected	SKZ 9198L
Policy No.		Coverage (\$)	0.00
Claim No.	C10007627	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	19/10/2020

### 2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	RU11107920	Colour	WHITE
Odometer	38240	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	FIRENZA	6 mm
L/H Front Tyre	215/55 R17	FIRENZA	6 mm
R/H Rear Tyre	215/55 R17	FIRENZA	6 mm
L/H Rear Tyre	215/55 R17	FIRENZA	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	16/10/2020	Inspection Date	19/10/2020
Survey held at	SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------