

ASS. REC. BY:

Steve

REF:

A16

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 3044M

Yr Regn:

23/6/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai T-40

c.c 1685

Colour:

Blue

A/C: Insured / Std / NI / N

Sp. Reading

427836

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

KMH18414MG4091494

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

225/60R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

18/10/20

D.O.A.

19/10/20

Survey held at

Com fort de l'gr

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prell. Report

Date/Time, File Return to?



: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

) \$ + RS. \$

Photos

Others

TOTAL

Rep. Form:

Comp Sum / L.E. /

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

27, Bras Basah Road, Singapore 189551
 Tel: 6354 1111 Fax: 6354 1112

Service Centres

27, Bras Basah Road, Singapore 189551 59, Loring Road, Singapore 109609
 45, Banting Road, Singapore 670496 383, Sin Ming Drive, Singapore 5147
 7, Bungeo Road, Singapore 120151 320, Ulu Road, Singapore 109649
 24, Serangoon Road, Singapore 358158

6553 1111

SPARK Assist
 Recovery Towing Accident

Approved Partners



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition

1. Date: 18/10/20 Time Received: 1115		3. Vehicle Type: ☐ Private ☐ Taxi (CTPL/CCPL) ☒ Fleet ☐ STK (Boon Lay)		4. Type of Towing: ☐ Normal Tow ☒ King Dolly ☐ Flat Bed ☐ Crane-up	
2. ☐ New ☐ SPARK Kakis Name of Customer: 712061 Contact No.: 91284078 Vehicle No.: SHP3044M Make / Model / Colour: 14U Email:		5. Nature of Service: ☐ Jumpstart ☒ Recovery ☐ Change Tyre / Battery		6. Parts Replaced/Remarks:	

7. Location: BLVD35 RedDek M4L

9. Preferred Workshop:

- | | | |
|-----------------------------------|--|--|
| ☐ Braddell | ☒ Loyang | ☐ Pandan |
| ☐ Sin Ming | ☐ Sungei Kadut | ☐ Ubi |
| ☐ Senoko | ☐ Komoco (UBI / Leng Kee) | ☐ Cycle & Carriage (PD) |
| ☐ Others: | | |

8. Vehicle Tow - In Workshop:

- | | |
|--|--|
| ☐ Smoky Exhaust | ☐ Wheel Jammed |
| ☐ Overheating | ☐ Steering Faulty |
| ☐ Brake Faulty | ☐ Alternator Faulty |
| ☐ Starting Problem | ☐ Loss Power |
| ☒ Accident | ☐ Engine Stalled |
| ☐ Return Taxi | |


10. Odometer Reading :

Fuel Level : F 1/4 1/2 3/4 E

11. Radio / CD Player

- ☐ OK
☐ Faulty
☐ Not tested

Job Attended



: Cracked X : Dented
 / : Scratched O : Missing

Signature of Customer

12. Tow Truck / Recovery Van : ☐ VRS ☒ QA ☐ GAO ☐ TZ ☐ YISHUN ☐ OTHERS

Name of Driver : JOL

Vehicle No. : 7K7646

Time Dispatch : 1115

Time of Arrival : 1145

Time Completed : 1215

Cash Invoice Details (if applicable)

13. Cash Invoice No. :

Customer Acknowledgement

- a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
 b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
 c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

18/10/20

Date

1145

Time

[Signature]

Signature of Customer

4. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard