

COMFORTDELGRO PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA6614P

17/10/20

MAKE :

MODEL HYU- I40

CHIANG/ AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER / <i>MC</i>			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH X		\$35.60	\$71.20
10	REAR BUMPER CLIPS / <i>MC</i>		\$2.20	\$22.00
1	REAR BUMPER REFLECTOR LH ?			\$32.00
1	REAR BUMPER REINFORCEMENT ?			\$428.40
1	REAR BUMPER UNDER COVER ?			\$228.00
1	LH EXHAUST SILENCER ?			\$967.70
1	REAR CENTRE EXHAUST PIPE ?			\$730.10
				\$3,585.40
				\$717.08
				\$2,868.32
				20.00%
				DISCOUNTED TOTAL
1	REAR BUMPER MAT / <i>MC</i>			\$50.00
1	REVERSE SENSOR / <i>shorted</i>			\$135.70
				\$185.70
	Labour Charge			
	Panel Beating			\$480.00 <i>280</i>
	Spray Painting Charge			\$300.00 <i>200</i>
	Remove/refix reverse sensor			\$60.00 <i>30</i>
	Remove/refix exhaust pipe			\$90.00 <i>?</i>
	Tuff Kote			\$90.00 <i>X</i>
				\$1,020.00
				\$4,074.02
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Steve (LKK) with Phil
19/10/20, 3.30pm

L/S

My ALsy
2 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ENGINEERING

of COMFORTDELGRQ

ARC Repair TP(CLSO)1

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pongalan Road Singapore 650226

220 Hill Road Singapore 912001

24 Senoko Loop Singapore 758156

7 Sungai Kadut Way Singapore 728791

501 Ashun Industrial Park A Singapore 758753

Date/Time 19-10-2020 13:59

Page : 1

JOB CARD Sales Order:

JC NO.: 305428778

COMFORT TRANSPORTATION PTE LTD

7010045

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(O)

(R)
(P)

COUNT CARD NO.

REGN NO SHA6614P

MILEAGE

MAKE : HYUNDAI

FUEL

E 1/2 F

MODEL I-40

DATE/TIME IN 19.10.2020 11:10

YR OF MANUF 30.04.2014

TARGET DATE


CHASSIS NO KMFLB411MEU053798

COMPLETION DATE/TIME:

Accident Date: 17.10.2020
NATURE: 3P 17.10.2020

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Vehicle No.: SHA6614P

CHIANG

Signature No.:

Exit Pass

Vehicle No.: SHA6614P

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

To be kept by Security Guard

returned to Service Reception upon collection