

Our Ref : 305428772

Date : 19/10/20

Time of Fax : _____

Via/Fax : Email

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

Workshop

Attn : Motor Claims Dept.

Dear Sirs

Your Insured : SLU2070G

Date of Acc : 17/10/20

* 8 pages

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SHD 69375

Loyang
59 Loyang Drive
Singapore 508969

1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.

2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

3 Enclosed, please find :

- I) Our initial estimate of repairs of the damaged vehicle.
- II) Accident report made by our client.

4 I would appreciate it if you could call us to arrange for the survey of the vehicle

→ Lim Kwok Eng Tel no. 62148355 or Hp no. 98240811
Jumani Bin Masudin Tel no. 62148315 or Hp no. 96355305
Lim Tien Siong Tel no. 62148398 or Hp no. 96358546
Chiang Liat Choon Tel no. 62148314 or Hp no. 92966006
Fauzy Bin Mokhtar Tel no: 62148319 or Hp no : 81259176
Larry Ng Tel: 6214 8316

5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.

6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

7 Thank you.

Yours faithfully



for Vice President

Crash Repairs & Claims Recovery

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 19.10.2020
Time: 13:42:42
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305428772
REGN NO : SHD6937S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.10.2015
DATE/TIME IN : 17.10.2020 20:30
ACCIDENT DATE : 17.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1 L	1,052.20	20.00	841.76
0002	04-01-0103-0638-G	I40VC BRKT ASSY-FR BPR UP	1 L	22.40	20.00	17.92
0003	04-01-0103-0640-G	I40VC BRACKET-FR BUMPER S	1 L	24.60	20.00	19.68
0004	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0005	04-01-0103-0654-G	I40V2 COVER-FR FOG BLANKI	1 L	41.60	20.00	33.28
0006	04-01-0103-2164-A	I40V3 GRILLE ASSY-RADIATO	1 L	1,480.00	20.00	1,184.00
0007	04-01-0103-2175-G	I40V3 SYMBOL MARK-H	1 L	39.50	20.00	31.60
0008	04-01-0103-2295-G	I40V3 LIP-FRONT BUMPER	1 L	54.90	20.00	43.92
0009	FNPS	NO PLATE(S) WITH TRIM COV	1 N	55.00	2.00-	55.00
0010	04-01-0103-0782-A	I40VC LAMP ASSY-HEAD RH#	1 L	1,388.00	20.00	1,110.40

SUB-TOTAL : 3,355.16

JOB NATURE

0000 L	PANEL BEATING	500.00
--------	---------------	--------

COMFORTDELGRO ENGINEERING PTE LTD

Date: 19.10.2020

REPAIR ESTIMATE

Time: 13:42:42

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305428772
REGN NO : SHD6937S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.10.2015
DATE/TIME IN : 17.10.2020 20:3
ACCIDENT DATE : 17.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0001 23-502	SPRAYPAINT ON AFFECTED AREA	450.00
0002 17-01	CHECK ALL LIGHTING	50.00

SUB-TOTAL : 1,000.00

TOTAL : 4,355.16

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :