

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 19.10.2020

Time: 13:42:42

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305428772
 REGN NO : SHD6937S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 08.10.2015
 DATE/TIME IN : 17.10.2020 20:30
 ACCIDENT DATE : 17.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1 L	1,052.20	20.00	841.76	/	CR4
0002	04-01-0103-0638-G	I40VC BRKT ASSY-FR BPR UP	1 L	22.40	20.00	17.92	X	
0003	04-01-0103-0640-G	I40VC BRACKET-FR BUMPER S	1 L	24.60	20.00	19.68	X	
0004	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	/	MC
0005	04-01-0103-0654-G	I40V2 COVER-FR FOG BLANKI	1 L	41.60	20.00	33.28	/	CUT
0006	04-01-0103-2164-A	I40V3 GRILLE ASSY-RADIATO	1 L	1,480.00	20.00	1,184.00	/	CUT
0007	04-01-0103-2175-G	I40V3 SYMBOL MARK-H	1 L	39.50	20.00	31.60	/	MC
0008	04-01-0103-2295-G	I40V3 LIP-FRONT BUMPER	1 L	54.90	20.00	43.92	X	
0009	FNPS	NO PLATE(S) WITH TRIM COV	1 N	55.00	2.00	55.00	/	DR
0010	04-01-0103-0782-A	I40VC LAMP ASSY-HEAD RH#	1 L	1,388.00	20.00	1,110.40	/	CUT
							SUB-TOTAL : 3,355.16	

JOB NATURE

0000 L

PANEL BEATING

500.00

280

Stew (CLKK) WL R
 20/10/20, 11:30u
 2 days
 LIS
 My AL SJ

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 19.10.2020
Time: 13:42:42
Page: 2

JOY ENGINE
Number of Copies
3300
TOMER

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305428772
REGN NO : SHD6937S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.10.2015
DATE/TIME IN : 17.10.2020 20:3
ACCIDENT DATE : 17.10.2020

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 23-502	SPRAYPAINT ON AFFECTED AREA	200		450.00		
0002 17-01	CHECK ALL LIGHTING	30		50.00		
SUB-TOTAL						: 1,000.00

TOTAL : 4,355.16

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

FORTEL GRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579501
 Malacca : 85 6383 6280 Farquhar : 85 6280 9755

Workshops
 59 Luyang Drive Singapore 508988 24 Serangoon Loop Singapore 758156
 383 Sin Ming Drive Singapore 575717 7 Sengkang Kallit Way Singapore 728791
 46 Pandan Road Singapore 209006 601 Yishun Industrial Park A Singapore 768732
 220 Upper Macao Road Singapore 200000

Member of COMFORTDELGRO

Date/Time 18.10.2020 11:38

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.: 305428772

TOMER COMFORT TRANSPORTATION PTE LTD		REGN NO. SHD69378	MILEAGE
MS 7010045		MAKE : HYUNDAI	FUEL E 1/2 F
TOMER NO. 383 SIN MING DRIVE		MODEL I-40	17.10.2020 20:30
RESS Singapore SINGAPORE 575717		YR OF MANU 08.10.2015	TARGET DATE
(R) 65508755	(O)	CHASSIS CODE KMH341UMGU078450	COMPLETION DATE/TIME:
(P)			

COUNT CARD NO.

JOB DESCRIPTION


Accident Date: 17.10.2020

NATURE: 3P 17.10.2020

S/NO

LABOR CODE

DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

No.: SHD6937S LKE

Exit Pass

Vehicle No.: SHD6937S

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard