

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





| NTUC INCOME INSURANCE CO-OPERATIVE LTD                                 |  |  | Ref:   | NS/INC20011349/Eqf3q2 |                    |  |
|--|--|--|--------|-----------------------|--------------------|--|
| 73 BRAS BASAH ROAD<br>#05-01 NTUC TRADE UNION HOUSESINGAPORE<br>189556 |  |  | Date:  | 05-11-2020            |                    |  |
|  |  |  | Code:  | INC4                  |                    |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM                             |  |  |        |                       |                    |  |
|  | Insured Veh.   | SLN 7735B                                    | Veh. I | nspected              | SHD 7132R          |  |
|  | Policy No.   | 5101980399-01                                | Cover  | rage (\$)             | 0.00               |  |
|  | Claim No.  | MT/1107116-002                               | Exces  | ss (\$)               | 0.00               |  |
|  | Assign From  |  | Assig  | n Date                | 19/10/2020         |  |
| 2. Vehicle Particulars & Condition                                     |  |  |        |                       |                    |  |
|  | Make & Model   | HYUNDAI I40                                  | c.c    |                       | 1685               |  |
|  | Engine No.   | HIDDEN                                       | Year o | of Reg.               | 2016               |  |
|  | Chassis No.  | KMHLB41UMHU096281                            | Colou  | ır                    | BLUE               |  |
|  | Odometer   | 634984                                       | Steeri | ng                    | IN ORDER           |  |
|  | Brakes   | IN ORDER                                     | Modif  | ication               | STANDARD ALLOY RIM |  |
|  | General  | FAIR   |        |                       |                    |  |
| 3. Conditions of Tyres   |  |  |        |                       |                    |  |
|  |  | Size   | Make   |                       | Balance            |  |
|  | R/H Front Tyre   | 205/60 R16                                   | BRIDG  | ESTONE                | 5 mm               |  |
|  | L/H Front Tyre   | 205/60 R16                                   | BRIDG  | ESTONE                | 5 mm               |  |
|  | R/H Rear Tyre  | 205/60 R16                                   | BRIDG  | ESTONE                | 5 mm               |  |
|  | L/H Rear Tyre  | 205/60 R16                                   | BRIDG  | ESTONE                | 5 mm               |  |
| 4.   | Description of Damages   |  |        |                       |                    |  |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  |  |        |                       |                    |  |
|  | DAMAGES SEE DETAILS.   |  |        |                       |                    |  |
| 5.   | General Information  |  |        |                       |                    |  |
|  | Accident Date  | 17/10/2020                                   | Inspe  | ction Date            | 19/10/2020         |  |
|  | Survey held at   | ey held at COMFORTDELGRO ENGINEERING PTE LTD |        |                       |                    |  |
|  |  | 59 LOYANG DRIVE<br>SINGAPORE 508969          |        |                       |                    |  |
| 5a.  | Remarks  |  |        |                       |                    |  |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |        |                       |                    |  |
| 5b.  | Estimate Days of Repair  |  |        |                       |                    |  |
|  |  |  |        |                       |                    |  |

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: