



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 19/10/2020

User ID : GohKK2

Section A - Accident Details

Registration Number	SMB1568H
Case Reference Number	BUS/10/20/1018
Registration Date	23/12/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320H(AZZ)
Name of Driver	Muhammad Fauzie Bin Jamil
Type of Accident	Head To Side
Accident Date and Time	15/10/2020 4:10 PM
Accident Reported Date and Time	15/10/2020 6:15 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1568H-LEFT REAR PORTION SHB4261G COMFORTDELGRO TAXI (TP) INSURED WITH III
Prepared Date and Time	19/10/2020 3:44 PM
Chassis Number	WMAA22Z6F7002527
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$616.00	\$0.00
Total Spare Part Cost	\$1,016.80	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,222.80	\$0.00
Lump Sum Total	\$3,200.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	19/10/2020 3:54 PM	
Signature		<input checked="" type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 19/10/2020

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,590.00	795
Total Labour	\$1,590.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00	446
Total Spray Painting & Panel Beating	\$616.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			SMRT STICKER	1.00	\$200.00	0.00	\$200.00	Replace	✓
6010568	DOOR		FRAME, EXIT DOOR: FOR MAN A22 BUS	1.00	\$440.00	10.00	\$396.00	Replace	✓
6010498	DOOR	GV124M03	RUBBER, EXIT DOOR: FOR MAN A22 BUS	1.00	\$750.00	10.00	\$675.00	Replace	✓
6010499	DOOR	CV124M02	RUBBER, EXIT DOOR: FOR MAN A22 BUS	1.00	\$750.00	10.00	\$675.00	Replace	✓
Total					\$2,140.00		\$1,946.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

45
After pickup photo
Sun Pin (Lick)
20/10/2020
TP without prejudice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: