

Qvf3-1

77600001

ASS. REC. BY:

REF:

CS3/CTI/9015309/2018

Special Instructions:

JENNY LEW

ASSIGNMENT (Office)

20-10-2020

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

20/10/2020 4:25pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 9808L

Insured:

PC 643P

at Workshop m/s

K & M. Leasing

Tel:

97538067

of

51 ubi Avenue 1 # 03-18

Policy No:

Claim No:

SNM19D204048

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/08/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

5:01pm 29/8/19

Person Contacted:

Vicki

Vehicle

IN/OUT

Date/Time	Action/Instruction	Initials (X)
	GBH 9808L - NBA / CTI / 9015233 / Y	DOA: 28/8/2019
	PC 643P - NBA / CTI / 9015233 / Y	DOA: 28/8/2019
	Dismantle: 30/8/2019	
	After repair: 9/9/2019	
2/11/20	Submit LS \$4900 (Red 14,400, 75%), 8 days	

PRS

ASSIGNMENT

From: Date: 29/08/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 9808L

at Workshop m/s M Leasing

of 51 Ubi Ave 1 # 03-18

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4.9 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lwp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBH 9808L Yr Regn: 14/11/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace Van C.C. 2982

Colour: silver A/C: Insured / Std / NI / NA

Sp Reading: 16151 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTFHT02P800246/44

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or Steel Rim

Tyre Size: F: 195 R 15 C

R: 195 R 15 C

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 28/08/2019 D.O.I. 29/08/2019

Survey held at 4ck.

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

LeH.

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV = 60,000
	PV = 24459
	NV = 35,500
	Repair Day - 9 days
	Range - 9K - 10K
	RECEIVED 11 SEP 2019
	GBH 9808L No Estimate (PRS)
	30/8/2019

Date/Time, File Pass to? ☐ : Preli. Report

ij ☐ : Final Report

Date/Time, File Return to?

2) 2/11/20-Typist

Report Format: PRS

Lump Sum / L.B.E (\$) LS \$4900

Days Of Repair: 9 8

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 29 August 2019 4:25 PM
To: wanting@lawrencelee.com.sg
Cc: assignments
Subject: RE: OUR REF: SNM19D204048-PC643P-CBS - FW: ACCIDENT ALONG YISHUN INDUSTRIAL ST 1 ON 28.08.19 INVOLVING GBH9808L & PC643P (Our Ref: LWP/KMM/4324A/19/wt)

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: wanting@lawrencelee.com.sg [mailto:wanting@lawrencelee.com.sg]
Sent: Thursday, 29 August, 2019 4:12 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D204048-PC643P-CBS - FW: ACCIDENT ALONG YISHUN INDUSTRIAL ST 1 ON 28.08.19 INVOLVING GBH9808L & PC643P (Our Ref: LWP/KMM/4324A/19/wt)

Dear Boon Sen,

We refer to email below.

Please be informed that our clients object to the motor surveyors proposed by you.

Our clients propose to use one of the 8 motor surveyors below to conduct the joint pre-repair survey as the single joint expert:

Jayson Liaw	Fong Kok Heng
Chuah Poh Siong Gary	Dave Chang
Michael Yap	Danny Ho
Teo Liak Hoo	Dennis Yap

Kindly revert within two (2) working days by fax email to wanting@lawrencelee.com.sg.

Regards,

Tay Wan Ting (wanting@lawrencelee.com.sg)

Paralegal

For and On Behalf of

Lee Wee Peng Lawrence

Lawrence Lee & Co (UEN: 53159236K)

133 New Bridge Road #13-05 Chinatown Point Singapore 059413

tel. 6533 3680 fax. 6533 3689 email. info@lawrencelee.com.sg

This email is confidential and may be subject to legal privilege. If you are not the intended recipient, please delete this email and its contents/attachments immediately.

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: Thursday, 29 August 2019 3:14 PM

To: wanting@lawrencelee.com.sg

Subject: RE: OUR REF: SNM19D204048-PC643P-CBS - FW: ACCIDENT ALONG YISHUN INDUSTRIAL ST 1 ON 28.08.19 INVOLVING GBH9808L & PC643P (Our Ref: LWP/KMM/4324A/19/wt)

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Thursday, 29 August, 2019 2:41 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; wanting@lawrencelee.com.sg

Subject: OUR REF: SNM19D204048-PC643P-CBS - FW: ACCIDENT ALONG YISHUN INDUSTRIAL ST 1 ON 28.08.19 INVOLVING GBH9808L & PC643P (Our Ref: LWP/KMM/4324A/19/wt)

Dear Boon Sen,

Please conduct PRS for GBH9808L.

Note : officer in charge – Boon Sen 63896171.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: wanting@lawrencelee.com.sg [<mailto:wanting@lawrencelee.com.sg>]

Sent: Thursday, 29 August, 2019 11:01 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: ACCIDENT ALONG YISHUN INDUSTRIAL ST 1 ON 28.08.19 INVOLVING GBH9808L & PC643P (Our Ref: LWP/KMM/4324A/19/wt)

Dear Sirs,

We refer to the above matter.

Please see attach herewith the Notice of Accident of even date for your attention.

Regards,

Tay Wan Ting (wanting@lawrencelee.com.sg)
Paralegal

For and On Behalf of

Lee Wee Peng Lawrence

Lawrence Lee & Co (UEN: 53159236K)

133 New Bridge Road #13-05 Chinatown Point Singapore 059413

tel. 6533 3680 fax. 6533 3689 email. info@lawrencelee.com.sg

This email is confidential and may be subject to legal privilege. If you are not the intended recipient, please delete this email and its contents/attachments immediately.

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

LAWRENCE LEE & CO

Advocates & Solicitors

李伟平律师楼

UEN: 53159236K

Your ref: please advise

Our ref: LWP/KMM/4324A/19/wt

133 New Bridge Road #13-05

Chinatown Point Singapore 059413

tel: 6533 3680 fax: 6533 3689

email: info@lawrencelee.com.sg

29 August 2019

China Taiping Insurance (Singapore) Pte Ltd

EMAIL

Dear Sirs

**NOTICE OF ACCIDENT PURSUANT TO THE NIMA PROTOCOL
ACCIDENT ALONG YISHUN INDUSTRIAL ST 1 ON 28.08.19
INVOLVING GBH9808L & PC643P**

We are instructed by K & M Electrical Pte Ltd to notify you of the abovementioned road traffic accident involving our client's vehicle registration number GBH9808L and vehicle registration number PC643P owned your insured and driven by their servant/agent one Li Jiangchao at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

We do hereby notify you that our client's damaged vehicle may be inspected at the workshop at K & M Leasing Pte Ltd at 51 Ubi Avenue 1 #03-18 Paya Ubi Industrial Park Singapore 408933 (contact person: Vicki, mobile phone: 9753 8067).

Kindly revert within two (2) working days by fax or by email to wanting@lawrencelee.com.sg.

Yours faithfully



LEE WEE PENG LAWRENCE

Cc client

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/08/2019 09:33
Date Of Accident	28/08/2019 08:30
Exact Location Of Accident	YISHUN INDUSTRIAL ST 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH9808L
Insured/Policyholder	
Name Of Registered Owner	K & M ELECTRICAL PTE LTD
Co Reg No	200912721Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE VAN TURBO 5DR MT
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	AVCPSB0093861800
Cover Note Number	

Driver

Name of Driver	KRISHNAN ANBARASAN
Passport No/FIN	G2390331N
Date Of Birth	11/02/1992
Occupation	OUTDOOR
Date Of Driving Pass	16/04/2015
Driving Experience	4 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98077600
Fax Number	
Contact Number	OFFICE-98077600
Email Address	NOEMAIL

Address	51 ADMIRALTY ROAD WEST #B-03-18 COCHRANE LODGE 1
Postcode	757443
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHUAH KOK SEONG GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8529999 - FAX NO: 68522299
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190828/2151.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC643P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	LI JIANGCHAO
NRIC/Passport Number	G2596646K

Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	CHUAH KOK SEONG
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	GBH9808L
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report - TWA 1001871.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Police Report



**SINGAPORE
POLICE FORCE**



T/20190828/2151

1 of 3

Police Station Of Origin
Yishun North N P C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No: T/20190828/2151

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 28/08/2019 20:50		Vide Report No.		Station Diary No. 110	
Informant's Particulars					
Name of Informant: KRISHNAN ANBARASAN			Address: 51 Admiralty Road West #B-03-18 Cochrane Lodge 1 SINGAPORE 757443		
ID Type / ID No. FIN NO / G2390331N			Contact No. Home/Office: Mobile: 98077600		
Nationality INDIAN			Email:		
Sex: Male	Age: 27	Date of Birth: 11/02/1992	Type of Informant Driver		
Race: Indian			Language: English		Institution / School Name:
Occupation: Van driver			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 28/08/2019 08:30	Type of Location: Straight Road
Location: Along Road 1 YISHUN INDUSTRIAL STREET 1 Yishun Industrial Street 1 toward Yishun Ave 9 near to building North View Bizhub				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBH9808L	Van	TOYOTA		Grey	Seriously Damaged	1
PC643P	Bus/Coach/Mi nibus	SCANIA		Red	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report



**SINGAPORE
POLICE FORCE**



T/20190828/2151

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

2 of 3

Report No: T/20190828/2151

CONTINUATION OF REPORT

Driver			
Name	KRISHNAN ANBARASAN		ID No. G2390331N
Related Vehicle	GBH9808L (Van)		Contact No. 98077600
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LI JIANGCHAO		ID No. G2596646K
Related Vehicle	PC643P (Bus/Coach/Minibus)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 28.08.2019 at about 0830hrs, I am driving my company van GBH9808L at along Yishun Industrial Street 1 toward Yishun Ave 9 with a front passenger. I am driving my van on the right lane along Yishun Industrial Street 1 beside the building North View Bizhub. There was a bus PC643P which was travelling on my left side. The bus made a right turn toward North View Bizhub and hit the left passenger door of my van. After the accident, my passenger (Chuah Kok Seong FIN: G2998845K DOB: 19-01-1996 work permit No: 406111946 Malaysian national) HP 98801257 complain of pain on the left shoulder. There were scratches seen on the left shoulder. My passenger went to a clinic at B/620 Hougang and see a doctor and he was given 4 day of medical leave. Damaged to the van: left passenger door dented and scratches at the whole left side of the van. I has no injury.

Police Report



**SINGAPORE
POLICE FORCE**



T/20190828/2151

Police Station Of Origin:
Yishun North N.P.C.
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

3 of 3

Report No. T/20190828/2151

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

L/

SI YEO HWEE BENG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

28/08/2019 20:50

Officer In Charge Of Case:

TP / AEIT /

SI ANG YI TING, STEPHANIE

Contact No.: 65476414

Classification Of Case:

SN 085

Authentication Stamp

NP168

Singapore Police Force

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 721Z

Vehicle Details

Vehicle No.: GBH9808L

Vehicle to be Exported: No

Intended Deregistration Date: 29 Aug 2019

Vehicle Make: TOYOTA

Vehicle Model: HIACE VAN TURBO 5DR MT

Primary Colour: Silver

Manufacturing Year: 2018

Engine No.: 1KD2827733

Chassis No.: JTFHT02P800246144

Maximum Power Output: -

Open Market Value: \$28,136.00

Original Registration Date: 14 Nov 2018 ✓

First Registration Date: 14 Nov 2018

Transfer Count: 0

Actual ARF Paid: \$1,407.00 X

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 13 Nov 2028 ✓

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$26,563.00

COE Rebate Amount: \$24,459.00

Total Rebate Amount: \$24,459.00 ✓

The information contained herein is correct as at 29 Aug 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	GBH9808L
Vehicle Type:	A50 - Goods (Closed) Van/Van Panel (Delivery)
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Chassis No.:	JTFHT02P800246144
Propellant:	Diesel
Engine No.:	1KD2827733
Engine Capacity:	2982 cc
Maximum Power Output:	-
Maximum Laden Weight:	2800 kg
Unladen Weight:	1700 kg
Year Of Manufacture:	2018
Original Registration Date:	14 Nov 2018
Lifespan Expiry Date:	13 Nov 2038
COE Category:	C - Goods Vehicle & Bus
PQP Paid:	\$26,563.00
COE Expiry Date:	13 Nov 2028
Road Tax Expiry Date:	13 Nov 2019
Inspection Due Date:	13 Nov 2019
Intended Transfer Date:	29 Aug 2019
CO2 Emission:	210.00 (g/km)
CEV/VES Rebate Utilised Amount:	-
CO Emission:	0.066000 (g/km)
HC Emission:	0.002653 (g/km)
NOx Emission:	0.107000 (g/km)
PM Emission:	1.600000 (mg/km)

The current road tax expiry is 13 Nov 2019. You may renew the road tax from 14 Aug 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 13 Nov 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 14 Nov 2019 to 13 May 2020)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	0.00	-	0.00
Total Amount Payable:			25.00

Amount Payable (From 14 Nov 2019 to 13 Nov 2020)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	0.00	-	0.00
Total Amount Payable:			25.00

Message

This vehicle has a road tax Over Payment of \$91.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

You may print this page for reference.

OK

Print

Roadshow Exclusive
T&Cs apply

sgCarMart Carnival
31 Aug - 1 Sep 2019
 10am - 8pm
 Downtown East
 (next to Open Carpark B)
VISIT US!

Car Make / Model

Price Range

Depreciation

Year Reg

Vehicle Type

Advanced Search

Used Car Comparison

--- Comparing 2 Vehicles ---

Toyota Hiace 3.0A

Toyota Hiace 3.0M



NO IMAGE AVAILABLE



NO IMAGE AV

Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Add to Shortlist

Use search bar above to select another car to compare.

Use search bar above to select another car to compare.

CAR DETAILS

Price	\$60,800 ✓	\$70,800	
Instalment	N.A.	N.A.	
Registration Date	13-Mar-2018	06-Jun-2018	
Manufactured	2017	2018	
Mileage	-	-	
Transmission	Auto	Manual	
Engine Cap	2,982 cc	2,982 cc	
Road Tax	-	-	
Power	-	-	
Curb Weight	1,800 kg	1,700 kg	
Features	-	2.8 Turbo Engine, 4 Door Auto Van, Dual Airbags, Built In Reverse Camera, Rear Cooler.	
Accessories	DVD Player, Reverse Camera And Sensors.	-	
Description	RARE. Front And Rear Air Con. 5 Doors. Low Mileage. Original LED Head Lamp. Retractable Both Side Mirror. Under Warranty.	Best Economical And Large Storage For Your Commercial Use. Almost New, Ready Stock Available, Free Servicing, Free Road Tax, Loan Or In House Available, Lowest Interest, Trade In Available, Call For Viewing. High Trade In Available And Attractive Interest Rate For In House Loan. Wait No More, Book Now Before It Is Out Of Stock!	
COE	\$13,016	\$29,901	
OMV	\$33,730	\$28,138	
ARF	\$1,687	\$1,407	
Depreciation	\$7,120 /yr ✓	\$8,070 /yr ✓	
No. of Owners	1	1	
Type of Vehicle	Van	Van	
Category	-	-	
Availability	Available	Available	
Remarks	Fuel type Diesel	Fuel type Diesel	

6800/yr
= 566
9 yrs 3mth

SELLER INFORMATION



Toyota Hiace Commuter 2.8A GL \$83,800 \$9,160 /yr 22-Oct-2018 2,754 cc - Bus Available

Fuel Type: Diesel

10/18 Toyota Hiace Commuter 2.8 GL, 14 Seater, New Model.

Tham One Automobile & Trading

Posted: 29-Aug-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Audio Upgrade for Any Budget

Want more than what your stock in-car entertainment system can offer? With 400 head units choose from, you'll definitely find "the one" that suits your needs. Prices from just \$170!

Find out more!



Toyota Hiace Commuter 2.8A GL High Roof \$77,777 \$8,500 /yr 22-Oct-2018 2,754 cc - Bus Available

Fuel Type: Diesel

High Roof New 14 Seater Toyota Commuter Model! Cheapest In SG! Full Accessories! Can Register Excursion Private Hire Or Private Bus. No Gimmicks! Call Our Sales Executive And Grab It Before It's Gone! Stock Is Limited. Able To Test Drive!

Net Link Partners Pte Ltd

Posted: 20-Jul-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter 2.8A \$84,800 \$9,240 /yr 01-Nov-2018 2,754 cc - Bus Available

Fuel Type: Diesel

(Hiace Commuter With Front Sensing) Lots Of Safety Features! Come With Lots Of Accessories, High Loan With Low Interest Rate, High Trade In, Call Now To Find Out More!

Posted: 26-Aug-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 3.0A \$68,800 \$7,450 /yr 22-Nov-2018 2,982 cc - Van Available

Fuel Type: Diesel

Newly Registered! Totally Legit, GST/ARF/COE All In! Toyota Hiace 4 Doors Auto Diesel. Borneo Motors 3 Years Or 100k Km Warranty! Cheap! Hurry Call Now! 24 Hours Serving You!

ASWIN (1994) Pte Ltd

Posted: 29-Aug-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 2.8A Super GL Dark Prime \$74,800 \$8,090 /yr 23-Nov-2018 2,754 cc 17,056 km Van Available

Fuel Type: Diesel

Original Condition, Under Warranty, Bank/Finance, Welcome Trade-In, Previous Owner Usage For Fetch Kid.

SG Motor Link Pte Ltd

Posted: 29-Aug-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter 3.0A High Roof \$86,800 \$9,340 /yr 12-Dec-2018 2,982 cc 6,000 km Bus Available

Fuel Type: Diesel

Superb Condition Maintained By Owner With Care And Mileage Clocked Less Than 6000 Km And Still Under Borneo Motors Warranty. Call Us Now To Arrange For Viewing And Test Driving.

Ball Auto Pte Ltd

Posted: 21-Aug-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Model Price Depreciation Eng Cap Mileage Veh Type

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & CPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carback rates & car insurance. Find buy used Toyota Hiace, Toyota Hiace Singapore, used Toyota Hiace Singapore, used Toyota Hiace, used vehicles Singapore or even buy used Toyota Hiace Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no warranty can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions, or warrant the accuracy of this information.

Follow sgCarMart.com

About Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.



DOWNTOWN EAST
31 AUG - 01 SEP 2019
10AM TO 8PM



WIN a 201N stay at Amara
Sanctuary Resort Sentosa
AND
MOBIL 1 Engine Oil Giveaway!



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!



Direct Owner

Post an Ad

Advertiser Login

Ways of Selling

Free VICOM evaluation
Free grooming and 8 months maintenance
In-house workshop ensures quality service
Member of SVTA and hire purchase association
100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted 20 results/page

15 vehicles

Toyota Hiace

Search Selection	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Availability
Toyota Hiace		Any	Any	2018	Any	Any	Any	Available
	Toyota Hiace Commuter 3.0A Fuel Type: Diesel Previous Owner Strike 4d Hence Upgrading His Vehicle To Latest Facelift Model Super Low Mileage Of 8k. Car Under Utilized. Call Now To View This Lucky Vehicle. ABWIN Bus Pte Ltd	\$79,888	\$9,350 /yr	12-Mar-2018	2,982 cc	8,432 km	Bus	Available
Posted: 25-Jun-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, Toyota Hiace, Toyota Hiace, Toyota Hiace, Hiace, Used Toyota								
	Toyota Hiace 3.0A Fuel Type: Diesel RARE. Front And Rear Air Con. 5 Doors. Low Mileage. Original LED Head Lamp. Retractable Both Side Mirror. Under Warranty.	\$60,800	\$7,120 /yr	13-Mar-2018	2,982 cc	-	Van	Available
Posted: 10-Aug-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota								
	Toyota Hiace Commuter 3.0A Fuel Type: Diesel All-In Price! No Gimmicks/Hidden Costs! 100% Bank Or In-House Loan With Low 2.xx% Interests! High Trade-In Upon Viewing. Please Call Us Now! SG Motor Link Pte Ltd	\$83,888	\$9,710 /yr	18-Apr-2018	2,982 cc	83 km	Bus	Available
Posted: 26-Aug-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota								
	Toyota Hiace 3.0M Fuel Type: Diesel Well Maintained Low Mileage, Flexible Loan Arrangements? Please Call For More Details.	\$60,888	\$6,950 /yr	31-May-2018	2,982 cc	32,000 km	Van	Available
Posted: 28-Aug-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota								
	High Quality CF Spoiler For BMW 3 Series BMW E92 Carbon Fibre Spoiler (For 3 Series) Good Fitment. Using high quality Carbon Fibre Material. Find out more!							
	Toyota Hiace 3.0M Fuel Type: Diesel Best Economical And Large Storage For Your Commercial Use. Almost New, Ready Stock Available, Free Servicing, Free Road Tax, Loan Or In House Available, Lowest Interest, Trade In Available, Call For Viewing. High Trade In Available And Attractive Interest Rate For In Ho...	\$70,800	\$8,070 /yr	06-Jun-2018	2,982 cc	-	Van	Available
Posted: 23-Jul-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota								
	Toyota Hiace 3.0A DX Fuel Type: Diesel Toyota Hiace Original 5 Door Glass Panel, Original Rear Aircon, Original LED Head Lamps System, Original Retractable Side Mirrors, Original Security Key System, Nice Bidded Number Plate To Go Along.	\$72,000	\$8,200 /yr	08-Jun-2018	2,982 cc	-	Van	Available
Posted: 16-Aug-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota								
	Toyota Hiace Commuter 3.0A Fuel Type: Diesel Sliding Power Door Like New 1 Year Road Tax 13 Seaters Mini Bus For Sales! 3 Years Or 100000km Warranty Whichever Come First, 100% Loan And High Trade In. Can Register Excursion, Private Hire, Or Private Bus, Call Our Friendly Sales Executive And Find Out More! Tak Hiat Automobile	\$78,800	\$8,920 /yr	28-Jun-2018	2,982 cc	288 km	Bus	Available
Posted: 16-Aug-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota								
	Toyota Hiace Commuter 2.8A Fuel Type: Diesel \$84888 Is The Price For New Register Vehicle, No Additional Top Up Requires. 100% Easy Bank Or In House Loan With Low Interests Available! Please Call Us Now Or Simply Come On Down To Our Double Storey Showroom To View! Call Now To Look For Our Friendly S... SG Motor Link Pte Ltd	\$83,888	\$9,360 /yr	14-Aug-2018	2,754 cc	-	Bus	Available
Posted: 24-Aug-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota								
	Toyota Hiace 2.8A Fuel Type: Diesel Euro 6 Model, Prices Inclusive Of ARF, Register Fee, GST And COE. Up To 100% Loan/7 Years. Call Now For Enquiries, While Stock Last. Trade In Available.	\$71,800	\$7,990 /yr	21-Aug-2018	2,754 cc	-	Van	Available
Posted: 27-Jul-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota								

Compare

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Sep 2019		10 Sep 2019 15:09 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	K & M ELECTRICAL PTE LTD , Co. Reg. No.: 200912721Z		
Vehicle Reg. No.:	GBH9808L	Date of Loss:	28/08/2019 08:00 - :59 [9 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D204048C02	Policy/Cover Note No.:	DMB1SN18258918000
Vehicle Reg. No. (Insured):	PC643P	Policy No. (Claimant):	AVCPSB0093861800
		Excess:	S\$0.00
Repairer:	K & M Leasing Pte Ltd (HQ) K & M Leasing Pte Ltd, 408933 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	Allied World Assurance Company, Ltd (HQ) - Tel: 62201188		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 19/09/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBH9808L (SNM19D204048C02)**
[PC643P]

TP

K & M ELECTRICAL PTE LTD
































Aug 28 2019 8:00AM






















































[-]
















































K & M Leasing Pte Ltd

























Upload Documents Upload Photos Compose New Letter

View View in Browser ▼















Assessment Reports			1 per page ▼	✓
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	29/08/19 09:50	Accident Statement	 Load HTM	
Photos/Images			3 per page ▼	✓
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	29/08/19 09:41	Accident Photo [Linked Accident Report Documents]	 Load JPG	✓
2	29/08/19 09:41	Accident Photo [Linked Accident Report Documents]	 Load JPG	✓
3	29/08/19 09:41	Accident Photo [Linked Accident Report Documents]	 Load JPG	✓
4	29/08/19 09:41	Accident Photo [Linked Accident Report Documents]	 Load JPG	✓
5	29/08/19 09:41	Accident Photo [Linked Accident Report Documents]	 Load JPG	✓
6	29/08/19 09:41	Accident Photo [Linked Accident Report Documents]	 Load JPG	✓
7	29/08/19 09:41	Accident Photo [Linked Accident Report Documents]	 Load JPG	✓
8	29/08/19 09:41	Accident Photo [Linked Accident Report Documents]	 Load JPG	✓
9	29/08/19 09:41	Accident Photo [Linked Accident Report Documents]	 Load JPG	✓
10	29/08/19 09:41	Accident Photo [Linked Accident Report Documents]	 Load JPG	✓
11	29/08/19 09:41	Accident Photo [Linked Accident Report Documents]	 Load JPG	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/09/19 16:27	General View	 Load JPG	✓
2	10/09/19 16:27	General View	 Load JPG	✓
3	10/09/19 16:27	General View	 Load JPG	✓
4	10/09/19 16:27	General View	 Load JPG	✓
5	10/09/19 16:27	General View	 Load JPG	✓
6	10/09/19 16:27	General View	 Load JPG	✓
7	10/09/19 16:27	General View	 Load JPG	✓
8	10/09/19 16:27	General View	 Load JPG	✓
9	10/09/19 16:27	General View	 Load JPG	✓
10	10/09/19 16:27	General View	 Load JPG	✓
11	10/09/19 16:27	General View	 Load JPG	✓
12	10/09/19 16:27	General View	 Load JPG	✓
13	10/09/19 16:27	General View	 Load JPG	✓
14	10/09/19 16:27	General View	 Load JPG	✓
15	10/09/19 16:27	General View	 Load JPG	✓
16	10/09/19 16:27	General View	 Load JPG	✓
17	10/09/19 16:27	General View	 Load JPG	✓
18	10/09/19 16:27	General View	 Load JPG	✓
19	10/09/19 16:27	General View	 Load JPG	✓
20	10/09/19 16:27	General View	Load JPG	✓
21	10/09/19 16:27	General View	Load JPG	✓
22	10/09/19 16:27	General View	Load JPG	✓

Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
23	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
24	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
25	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
26	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
27	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
28	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
29	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
30	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
31	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
32	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
33	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
34	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
35	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
36	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
41	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
42	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
43	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
44	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
45	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
46	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
47	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
48	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
49	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
50	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
51	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
52	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
53	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
54	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
55	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
56	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
57	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
58	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
59	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
60	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
61	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
62	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
63	10/09/19 16:27	General View	 Load JPG	<input checked="" type="checkbox"/>
64	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	☑
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
76	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
77	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
78	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
79	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
80	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
81	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
82	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
83	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
84	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
85	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
86	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
87	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
88	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
89	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
90	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
91	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
92	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
93	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
94	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
95	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
96	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
97	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
98	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
99	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
100	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
101	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
102	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
103	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
104	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
105	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
106	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
107	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
108	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
109	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
110	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
111	10/09/19 16:35	Photographs of Damaged Parts	 Load JPG	☑
112	10/09/19 16:36	Photographs of Damaged Parts	 Load JPG	☑
113	10/09/19 16:36	Photographs of Damaged Parts	 Load JPG	☑
114	10/09/19 16:36	Photographs of Damaged Parts	 Load JPG	☑
115	10/09/19 16:36	Photographs of Damaged Parts	 Load JPG	☑
116	10/09/19 16:36	Photographs of Damaged Parts	 Load JPG	☑
117	10/09/19 16:36	Photographs of Damaged Parts	 Load JPG	☑
118	10/09/19 16:36	Photographs of Damaged Parts	 Load JPG	☑
119	10/09/19 16:36	Photographs of Damaged Parts	 Load JPG	☑
120	10/09/19 16:36	Photographs of Damaged Parts	 Load JPG	☑
121	10/09/19 16:36	Photographs of Damaged Parts	 Load JPG	☑
122	10/09/19 16:36	Photographs of Damaged Parts	 Load JPG	☑
123	10/09/19 16:36	Photographs of Damaged Parts	Load JPG	☑
124	10/09/19 16:36	Photographs of Damaged Parts	Load JPG	☑
125	10/09/19 16:36	Photographs of Damaged Parts	Load JPG	☑
126	10/09/19 16:36	Photographs of Damaged Parts	Load JPG	☑
127	10/09/19 16:36	Photographs of Damaged Parts	Load JPG	☑
128	10/09/19 16:36	Photographs of Damaged Parts	Load JPG	☑

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
129	10/09/19 16:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	10/09/19 16:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	10/09/19 16:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	10/09/19 16:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	10/09/19 16:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
134	10/09/19 16:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
135	10/09/19 16:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
136	10/09/19 16:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
137	10/09/19 16:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
138	10/09/19 16:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
139	10/09/19 16:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
140	10/09/19 16:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
141	10/09/19 16:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
142	10/09/19 16:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
143	10/09/19 16:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
144	10/09/19 16:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
145	10/09/19 16:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
146	10/09/19 16:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
147	10/09/19 16:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	29/08/19 09:42	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	29/08/19 09:42	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	29/08/19 09:42	Police Report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	29/08/19 09:42	Police Report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	29/08/19 09:42	Police Report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	29/08/19 09:50	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	29/08/19 09:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	29/08/19 09:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	29/08/19 09:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	29/08/19 09:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	29/08/19 09:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	29/08/19 09:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	29/08/19 09:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	29/08/19 09:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	29/08/19 09:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	29/08/19 09:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	29/08/19 09:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	29/08/19 09:42	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	29/08/19 09:42	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

Reset Save Print

There are no document checklists configured.

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119015309/QCD3S2

Date: 16/09/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN18258918000

Claimant Vehicle No: GBH9808L Insured Vehicle No: PC643P

Date of Loss: 28/08/2019 Nature of Claim: TP Claim No: SNM19D204048C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH9808L**

Make & Model: TOYOTA HIACE, 2.0 (M) Engine No: 1KD2827733

Reg. Date: 14/11/2018 (Man. Year: 2018) Chassis No: JTFHT02P800246144

Colour: Silver Odometer: 16151 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/09/2019

Date Inspected: 29/08/2019 Inspected At: K & M Leasing Pte Ltd
51 UBI AVE 1 #03-18
Singapore 408933

Estimated Period of Repair: 9.0 days

Adjuster: OI SUN PIN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000.00 - \$10,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Sep 2019)	
Parts:	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH9808L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >