

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
AUT	O & GENERAL IN	SURANCE (S) PL	Ref : CS/AGI20011411/I	Kqf3e2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date: 03-11-2020		
			Code: AGI		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLR 4168L	Veh. Inspected	SLW 8542L	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10007644KY	Excess (\$)	0.00	
	Assign From	ABIGAIL CHOO	Assign Date	21/10/2020	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA VEZEL (A)	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	RU11233003	Colour	METALLIC DARK GREY	
	Odometer	53938	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/60 R16	DUNLOP	8 mm	
	L/H Front Tyre	215/60 R16	DUNLOP	8 mm	
	R/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
	L/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	19/10/2020	Inspection Date	20/10/2020	
	Survey held at	160 SIN MING DRIVE #06-03			
	Repairer	MBM WHEELPOWER PTE LTD			
5a.	a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: