

(08/11/13) Wef

ASS. REC. BY: Marcus

REF:

CC6/QBE20011416/uds3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Yr Regn: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Colour: _____

Sp. Reading: _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / SRim / STD A/Rim or _____

Tyre Size: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. _____

mm

Rear

R/Bal. _____

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

D.O.I. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

have h.c.d

have video at folder

ATA # 22314 case 30-4-2028

cover 380.61 assy 1094.15 m.c.r.r 1201.42 door 2025

1/11/20 1/5 # 9200 confirmed with Alan

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: _____

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

) S + RS _____

) Photos _____

) Others _____

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48, AUTO BAY
SINGAPORE 417883

VEHICLE No: SLS 1577D

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ulu: Jiah

Not Authored
dhe
21/10/20
1/5 9200/
Homs.

1PC	FRONT BUMPER	Deep Cut	1481.22	\$1,688.20 ✓
1PC	FRONT BUMPER REINFORCEMENT	11		\$713.50 X
2PCS	FRONT BUMPER CHROME MOULDINGS @165.00	161 x 22 = 322.00		\$330.00 ✓
1SET	FRONT BUMPER RIVET	nee		\$50.00 ✓
1PC	HEADLAMP O/S	11		\$1,860.25 X
1PC	FRONT FENDER O/S	11		\$971.35 X
1PC	FRONT FENDER EMBLEM O/S	nee		\$98.20 ✓
1PC	FRONT FENDER CHROME MOULDING O/S	nee	80.50	\$99.50 ✓
1PC	FRONT SHOCK ABSORBER O/S	Surf	645.25	\$866.20 ✓
1PC	FRONT KNUCKLE ARM O/S	Surf	755.30	\$1,045.50 ✓
1PC	FRONT KNUCKLE ARM BEARING O/S	Baye	455.00	\$485.00 ✓
1PC	FRONT TORSION ARM O/S	Surf	355.20	\$699.20 ✓
1PC	FRONT DOOR O/S	20/warp	2005.00	\$2,201.30 ✓
1PC	FRONT DOOR CHROME MOULDING O/S	nee	245.50	\$266.50 ✓
1PC	FRONT DOOR VIEW MIRROR COVER O/S	one		\$285.00 ✓
1PC	FRONT DOOR VIEW MIRROR ASSY O/S	one/baye	1201.42	\$1,850.20 ✓
1PC	FRONT DOOR VIEW MIRROR LAMP O/S	nee		\$235.00 X
1PC	FRONT DOOR GLASS OUTER CHROME MOULDING O/S	20/nee	345.01	\$366.20 ✓
1PC	FRONT DOOR OUTER HANDLE O/S	11		\$385.00 X
1PC	FRONT DOOR FRAME GARNISH O/S	nee		\$120.00 ✓
1PC	FRONT DOOR INNER RUBBER O/S	nee	330.00	\$399.00 ✓
2PCS	FRONT DOOR HINGES @210.00	11		\$420.00 X
1PC	REAR DOOR O/S	11		\$2,005.20 X
1PC	REAR DOOR OUTER CHROME MOULDING O/S	nee	225.00	\$250.50 ✓
1PC	REAR DOOR INNER RUBBER O/S	11		\$395.00 X
1PC	ROCKER PANEL GARNISH O/S	De/To, 11	665.00	\$855.20 ✓
1PC	REAR FENDER O/S	11		\$2,650.00 X
1PC	FRONT SPORT RIM O/S	Surf	800	\$1,200.00 ✓
				\$22,791.00

TO CHECK WIRING	\$80.00	20
TO CONDUCT WHEEL ALIGNMENT	\$150.00	80
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	\$180.00	150
TO DISMANTLE & REFIX FRONT DOOR MECHANISM	\$100.00	80
TO RESET & REPROGRAMME SYSTEM	\$100.00	50
TO SPRAY RUST PROOFING	\$100.00	30
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,200.00	500
TO PUTTY & SPRAY PAINTING	\$1,680.00	1200
TOTAL	\$26,501.00	

1043460

100

9391.14

9200

11501.14