




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI20011422/Uyf3q2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date : 10-11-2020	
				
			Code : AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SGZ 4550H	<b>Veh. Inspected</b>	SKW 357U
	<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	C10007667CH	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	ABIGAIL CHOO	<b>Assign Date</b>	21/10/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	NISSAN QASHQAI (A)	<b>c.c</b>	1997
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
	<b>Chassis No.</b>	SJNFBAJ11U1451063	<b>Colour</b>	PURPLE
	<b>Odometer</b>	42649	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	225/45 R19	YOKOHAMA	5 mm
	<b>L/H Front Tyre</b>	225/45 R19	YOKOHAMA	5 mm
	<b>R/H Rear Tyre</b>	225/45 R19	YOKOHAMA	5 mm
	<b>L/H Rear Tyre</b>	225/45 R19	YOKOHAMA	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	20/10/2020	<b>Inspection Date</b>	23/10/2020
	<b>Survey held at</b>	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	