

ASS. REC. BY:

REF:

A/G / 20011434/KP

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

160

05-03

Caris Motor

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

1.84

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Sheri

Vehicle: IN / OUT

Veh No:

SMF 3835C

Yr Regn: 05, 17

Type: M. Car

M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

c.c.

1498

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

60556

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRHFC16601HT000040

Gen. Cond:

Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

6

mm

L/Bal.

4

mm

L/Bal.

6

mm

D.O.A.

18/10/20

D.O.I.

22/10/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

01/5M

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/11

2217.84

Cubana

Date/Time, File Pass to?

☐

Prell. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$