

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

NEEL-1/sum

Date: 21.10.2020
Time: 13:39:39
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305429281
REGN NO : SHD6502M
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 10.09.2014
DATE/TIME IN : 21.10.2020 11:15
ACCIDENT DATE : 21.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	1,106.00	20.00	884.80	/	00
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	/	MC
0003 04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	228.00	20.00	182.40	X	NN
					907.40	SUB-TOTAL : 1,084.80	

JOB NATURE

0000 PB	PANEL BEATING		300.00	280
0001 SP	SPRAYPAINT CHARGE	510	300.00	200
0002 L	REMOVE/REFIX REVERSE SENSOR		80.00	30
SUB-TOTAL : 680.00				

TOTAL : 1,764.80

MVA NAME & SIGNATURE
DATE: 21/10/20

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE:

Steve (LKK) in PM
21/10/20, 2.30pm
2 Lys
L/S
M AL SLy

= 1412.40
L/S - 1129.92
= 1150

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: