

Our Job Ref No : 305430236

Date : 29. Oct. 2020

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156**FINALIZATION FORM**

To : LKK

Fax :

Attn : STEVE

Vehicle Reg No. : SHC 959Z

Date of Accident: 27. Oct. 2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **NTUC** **GBA8782U**
2. The finalized amount shall be:
- (a) Spare Parts after List discount \_\_\_\_\_
- (b) Labour Charges \_\_\_\_\_
- Total for Part-By-Part Repair Cost** \_\_\_\_\_
- (c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: **20%** \_\_\_\_\_  
**Final Lumpsum Repair cost** **\$3,750.00**

3. Estimated normal period for repairs:
- 3**
- working days.

- 4.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and  
finalized amountSignature : 

Name : Loke Wei Yieng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Steve

Date : 29/10/20

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: