





























RE-INSPECTION AFTER REPAIR



54500-3570A (2000)

NISSAN GROUP
LITHIUM TRANSVERSE 4x4
54500-3570A 1