

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

China Taiping CP(P)
LKK - Steve

Date: 21.10.2020
Time: 14:31:04
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305429285
REGN NO : SHD4900K
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 13.02.2020
DATE/TIME IN : 21.10.2020 12:10
ACCIDENT DATE : 21.10.2020

QTY IND UNIT-PRICE DISC% AMOUNT

JOB / PARTS DESCRIPTION

PART REQUISITION

0001 FNPS	NO PLATE(S)W/TRIM COVER	1 N	55.00		55.00	/	OR
0002 04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52	/	BR
0003 04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00	361.00	/	BR
0004 04-01-0104-2370-G	REAR BUMPER FOGLAMP	1	201.50	20.00	161.20	X	
0005 04-01-0104-2288-G	REAR BUMPER BEAM	1	294.80	20.00	235.84	/	BR
0006 04-01-0104-2545-G	REAR BUMPER LWR MOULDING	1	155.00	20.00	124.00	X	
0007 04-01-0104-2532-G	REAR BUMPER SIDE BRKT RH	1	33.10	20.00	26.48	X	
0008 04-01-0104-3919-G	REAR BUMPER STAY RH	1	138.10	20.00	110.48	X	
0009 04-01-0104-3819-G	REAR BUMPER STAY LH	1	138.10	20.00	110.48	X	
0010 04-01-0104-0852-G	REAR BUMPER REFLECTOR RH	1	31.90	20.00	25.52	X	
0011 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	/	PK
0012 04-01-0104-2544-G	REAR BUMPER TOW COVER	1	5.40	20.00	4.32	X	
0013 09-01-9999-0068-A	REVERSE SENSOR	1	135.70		135.70	/	BR

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

China Taiping CP (P)
LKK - Steve

Date: 21.10.2020
Time: 14:31:04
Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305429285
REGN NO : SHD4900K
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 13.02.2020
DATE/TIME IN : 21.10.2020 12:1
ACCIDENT DATE : 21.10.2020

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0014 04-01-0104-1150-A REAR BUMPER MAT	1		50.00		50.00
SUB-TOTAL					1,785.14

JOB NATURE

0000 PB	PANEL BEATING	350.00	320
0001 SP	SPRAYPAINT CHARGE	250.00	200
0002 L	R/I REVERSE SENSOR	120.00	30
SUB-TOTAL		720.00	

TOTAL : 2,505.14

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Steve (LKK) in MC
21/10/20, 3:30pm
P/P
My Be My
2 dys

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Hill Road Singapore 1047649

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

Date/Time: 21.10.2020 13:56

Page : 1

member of COMFORTDELGRO

JOB CARD Sales Order:

JC NO.:305429285

Team: ARC Repair TP(CLSO)1

COMER

AS 7010045
COMER NO. 383 SIN MING DRIVE
RESS Singapore SINGAPORE 575717
65508755 (O)

(R)

(P)

REGN NO. SHD4900K	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 21.10.2020 12:10
YR OF MANU. 13.02.2020	TARGET DATE
CHASSIS CODE KMHC851CVLU189453	COMPLETION DATE/TIME:


COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 21.10.2020
NATURE: 3P 21.10.2020

3/NO LABOR CODE

DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

Exit Pass

No.: SHD4900K

LIMITS

Vehicle No.: SHD4900K

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard