

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB5918P
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Oct 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Maroon
Manufacturing Year:	2019
Engine No.:	2ZR2F35079
Chassis No.:	JTDKB3FUX03089265
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	20 Dec 2019
First Registration Date:	20 Dec 2019
Transfer Count:	0
Actual ARF Paid:	\$14,530.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Dec 2027
PARF Rebate Amount:	\$10,897.00
Intended COE Rebate Details	
COE Expiry Date:	19 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$25,581.00
COE Rebate Amount:	\$22,884.00
Total Rebate Amount:	\$33,781.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 22 Oct 2020

OK

(L/C)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/10/2020 15:48
Date Of Accident	20/10/2020 07:40
Exact Location Of Accident	CHOA CHU KANG WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5918P
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	1XXXXX369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-20095484MFSH
Cover Note Number	

Driver

Name of Driver	TAY KIM HONG
NRIC No	SXXXX138H
Date Of Birth	21/05/1965
Occupation	OUTDOOR
Date Of Driving Pass	10/11/1987
Driving Experience	32 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JANICE TEO YI YUN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG KPE EXIT TOWARDS AIRPORT RD WITH A FEMALE PASSENGER. TRAFFIC WAS HEAVY AND A VEHICLE IN FRONT OF MY TAXI STOPPED. I APPLIED MY BRAKE TO STOP AND MANAGED TO STOP IN TIME. AFTER WHICH I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SKG8883Z HAD COLLIDED ONTO THE REAR OF MY TAXI. MY PASSENGER AND I WERE INJURED. I WILL BE GOING TO SEEK MEDICAL ATTENTION AFTER I LODGE THIS REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKU8308U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TUTTY ARRIANY BINTE KAMARUDIN
NRIC/Passport Number	SXXXX214B
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAY KIM HONG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHB5918P

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name JANICE TEO YI YUN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHB5918P

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

[illegible]

A-5HB5A18P

B-SK48308U

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I/We declare the foregoing particulars are true in every respect.

declare the fore

20/10/2020

20/10/2020

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Case Details

Case Reference Number :

TAX/10/20/2038

Type of Repair : Accident Repair

Vehicle Registration Number : SHB5918P

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-12942-ID

Assigned By : Tan Lee Ge #

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 19/10/2020 11:40 PM

Vehicle Age(In Months) : 10

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	485.60	485.60	25.00	364.20	Replace	1	364.20	Replace	✓ / CR4
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 1	2	4.00	8.00	25.00	6.00	Replace	2	6.00	Replace	✓ / Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	4.00	8.00	25.00	6.00	Replace	2	6.00	Replace	✓ / Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 3	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	✓ / Nec
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.30	22.60	25.00	16.95	Replace	0	0	Not Give	✓ X su
One Time Key In	Main			STOPPER, RR BUMPER, RH & LH	2	4.50	9.00	25.00	6.75	Replace	0	0	Not Give	✓ X su
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	132.60	132.60	25.00	99.45	Replace	0	0	Not Give	✓ X su
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	132.60	132.60	25.00	99.45	Replace	0	0	Not Give	✓ X su
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.50	45.00	25.00	33.75	Replace	10	33.75	Replace	✓ / Nec

Total Spare Part Cost 4,591.17

Surveyor Total 1,172.33

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 4,591.17

Final Sur Total 1,172.33

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			CLIP SEAL, RR BUMPER, RH & LH	2	2.50	5.00	25.00	3.75	Replace	0	0	Not Give	✓ Xsvc
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	374.50	374.50	25.00	280.88	Replace	1	280.88	Replace	✓ /CR4
One Time Key In	Main			RETAINER, OUTSIDE, RH & LH	2	3.90	7.80	25.00	5.85	Replace	0	0	Not Give	✓ Xsvc
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	22.00	22.00	25.00	16.50	Replace	1	16.50	Replace	✓ /scr
One Time Key In	Main			PAD, RR BUMPER, CTR	3	11.00	33.00	25.00	24.75	Replace	3	24.75	Replace	✓ /NEC
One Time Key In	Main			REAR BUMPER REFLECTOR ASSY, REFLEX, RH	1	39.00	39.00	25.00	29.25	Replace	0	0	Check	✓ X
One Time Key In	Main			REAR BUMPER REFLECTOR ASSY, REFLEX, LH	1	39.00	39.00	25.00	29.25	Replace	0	0	Not Give	✓ X
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	332.70	332.70	25.00	249.52	Replace	0	0	Check	✓ X
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	72.00	72.00	10.00	64.80	Replace	0	0	Check	✓ X
One Time Key In	Main			REVERSE SENSOR, REAR BUMPER	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	✓ X
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	175.10	175.10	25.00	131.32	Replace	1	131.32	Replace	✓ / Def
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	229.90	229.90	25.00	172.43	Replace	1	172.43	Replace	✓ / Def
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	241.90	241.90	25.00	181.43	Replace	0	0	Not Give	✓ Xsvc
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ /Nec
One Time Key In	Main			CLIP, FLOOR UNDER COVER, NO.1	10	3.20	32.00	25.00	24.00	Replace	0	0	Not Give	✓ Xsvc

Total Spare Part Cost 4,591.17

Surveyor Total 1,172.33

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 4,591.17

Final Sur Total 1,172.33

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			CLIP, FLOOR UNDER COVER, NO.2	10	3.90	39.00	25.00	29.25	Replace	0	0	Not Give	✓ X Sur.
One Time Key In	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	651.00	651.00	25.00	488.25	Replace	0	0	Check	✓ X Sur
One Time Key In	Main			END PANEL, COVER, DECK TRIM, REAR	1	126.70	126.70	25.00	95.03	Replace	0	0	Check	✓ X Sur
One Time Key In	Main			END PANEL, COVER, DECK TRIM SERVICE HOLE	1	48.50	48.50	25.00	36.38	Replace	0	0	Check	✓ X Sur
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	✓ X Sur
One Time Key In	Main			SPARE TYRE PANEL, PAN, REAR FLOOR	1	583.40	583.40	25.00	437.55	Replace	0	0	Not Give	✓ X Sur
One Time Key In	Main			PIPE ASSY, EXHAUST, TAIL	1	1,649.00	1,649.00	25.00	1,236.75	Replace	0	0	Not Give	✓ X Sur
One Time Key In	Main			SUPPORT, EXHAUST PIPE NO.5	1	49.10	49.10	25.00	36.83	Replace	0	0	Not Give	✓ X Sur
One Time Key In	Main			BRACKET, EXHAUST PIPE SUPPORT	1	41.80	41.80	25.00	31.35	Replace	0	0	Not Give	✓ X Sur
Total Spare Part Cost									4,591.17	Surveyor Total 1,172.33				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									4,591.17	Final Sur Total 1,172.33				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	676.00	200	✓
Total:			676.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	✓
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
Total:			918.00	200.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO RESPRAY REAR PANEL	180.00	0	
4	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	
Total:			918.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/
2	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	/
3	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	
4	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	
5	Main	TO REMOVE & REFIT EXHAUST	120.00	0	
6	Main	TO REPLACE SUNDRY PARTS	100.00	0	
7	Main	TO WASH AND VACUUM	60.00	0	
Total:			800.00	40.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,591.17	1,172.33
Total Labour Cost	676.00	200.00
Total Spray Painting	918.00	200.00
Other	800.00	40.00
Overall Total	6,985.17	1,612.33
Lump Sum Repair Option		<input type="checkbox"/>
Lump Sum Total	0.00	1,612.33
Surveyor Approved Amount		1,612.33
No of Repair Days*	5	3
Remarks	-	P/P, before paint photo

3 days

Estimator Assessment(\$)

Surveyor Assessment(\$)

Surveyor Name

Sun Pin (LKK)

Signature



Save

Clear

Survey Date

21/10/2020

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: