

Condition

COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 19.10.2020

Time: 16:16:31

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305428825
REGN NO : SIA1695M
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 16.06.2016
DATE/TIME IN : 19.10.2020 13:00
ACCIDENT DATE : 19.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1 L	1,106.00	20.00	884.80	✓	00
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	✓	NK
0003 04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1 L	228.00	20.00	182.40	X	NAI
0004 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	135.70	10.00	122.13	?	X NAI
0005 04-01-0103-0585-G	I40VC LAMP ASSY-RR COMB O ^{ch}	1 L	697.80	20.00	558.24	X	(NAI ONLY) CRA water marked
					902.40	SUB-TOTAL : 1,765.17	

JOB NATURE

0000 20-05	REAR BUMPER ADVERTISMENT LOGO	50.00	✓	NK
0001 L	PANEL BEATING	350.00	280	
0002 23-502	SPRAYPAINT ON AFFECTED AREA	250.00	200	
0003 17-01	CHECK ALL LIGHTING	50.00	30	
0004 20-22	REMOVE/REFIX REVERSE SENSOR	120.00	30	
SUB-TOTAL : 820.00				

Steve (LKK) WK PL
19/10/20, 4.19 PM
L/S
My AL sy
2 dgr

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: