

Our Job Ref No : 305428897

Date : 27. Oct. 2020

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**

To : LKK

Fax :

Attn : STEVE

Vehicle Reg No. : SHA6607K

Date of Accident: 19. Oct. 2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC WC5456Y
2. The finalized amount shall be:
- | | |
|---|-------------------|
| (a) Spare Parts after List discount | \$7,498.40 |
| (b) Labour Charges | \$1,850.00 |
| Total for Part-By-Part Repair Cost | \$9,348.40 |
| (c.) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | |
| Final Lumpsum Repair cost | |

3. Estimated normal period for repairs:
- 4
- working days.

- 4.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : 

Name : Loke Wei Yieng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Steve

Date : 27/10/20

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: