

ASSIGNMENT

CJB April 2026

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. D20004337 MVBC


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: QX 84E Yr Regn: 2006 / MayType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Odyssey C.C. 2354Colour: SILVER A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: K20 K24A63002168C/No: SHMRB18406C202168

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim STD A/Rim or

Tyre Size: F: 215/60 R16R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Dunlop

Front _____ Rear _____

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 24/10/2020 D.O.I. 26/10/2020Survey held at Chin Meng Keki Bldg.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The vehicle caught fire at the engine

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First Report.Compartment due to electrical in nature.Vehicle unsage to repair as both front chassis30/10 Sent Reli to Bryanexposed to high heat. Structural integrity compromised.MV 33.5KLVA 26KVehicle left 67 meters til CJB reping.MV 7.5K (estimated) using 6K dep (chasing below 86 cement18/11/20 Submit extensive total loss report(as not profit organization)

Date/Time, File Pass to?

: Prel. Report

Days Of Repair: _____

1) 18/11/20

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ 500)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S+RS \$ _____

Photos

Others

TOTAL

Report Format: Ob - T/L - E

Lump Sum / I.B.I. (\$) _____



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D20004337MVQC

Our Ref: ~~CS~~/FCI20011575/Dyf3

Date: 30 November 2020

The Motor Claims Department
M/s MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO QX84E

We thank you for the instruction on 26/10/20

Please be informed that we had conducted the inspection of the abovementioned vehicle on 26/10/20 at the premises of M/s CHIN MENG MOTORS and have the following to report:-

Workshop Estimate Amount : S\$ 0.00
Revised Estimate Amount : S\$ 0.00
"Check" Items Amount : S\$ _____
Market Value : S\$ 33,500.00
LTA Reimbursement Value : S\$ 26,000.00
Nett Value : S\$ 7,500.00

Description of Damage:

The vehicle caught fire

Comments/ Present Status:
Pending Investigation



Yours Faithfully

Bryan Ang
Licensed Appraiser

Morbella MX6 HD Digital Recorder.

$$MV \text{ use } 75K \text{ dep/year} = \frac{7500}{12} \times 67$$

$$MV = 41.8K$$

$$LTA = 25.8K \text{ (at 18 Nov 2020)}$$

$$NL = 16K \text{ (approximate)}$$

Additional remark:

Accessorie

\$ 229.00 (New at 2014)