

ASS. REC. BY: Sun Pin

REF:

CC4/LPC20011583/G/bu3**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: PC841J Yr Regn: 16/11/2011Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Scania K1B4X2 C.C. 8867Colour: Multicolour A/C: Insured / Std / NI / NA

Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: Ys 2K4X20001874302Gen. Cond: Good / Fail / Poor / BurntSteering: Inorder / 8 / Jammed / Leaked / Burnt orBrake: Inorder / 8 / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 295/80 R22.5R: 295/80 R22.5BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 11/10/2020

Survey held at

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 26/10/2020SC Auto

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: 110,000  
 PV: 3,398  
 NV: 106,602

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: \_\_\_\_\_

Lump Sum / L.B.H. (?) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. SI \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	260M
<b>Vehicle Details</b>	
Vehicle No.:	PC841J
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Oct 2020
Vehicle Make:	SCANIA
Vehicle Model:	KIB4X2 MANUAL ABS
Primary Colour:	Multicolor
Manufacturing Year:	2011
Engine No.:	6663509
Chassis No.:	YS2K4X20001874302
Maximum Power Output:	-
Open Market Value:	\$115,681.00
Original Registration Date:	16 Nov 2011
First Registration Date:	16 Nov 2011
Transfer Count:	0
Actual ARF Paid:	\$5,785.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	15 Nov 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$32,289.00
COE Rebate Amount:	\$3,398.00
<b>Total Rebate Amount:</b>	<b>\$3,398.00</b>

The information contained herein is correct as at 27 Oct 2020

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/10/2020 11:56
Date Of Accident	11/10/2020 19:20
Exact Location Of Accident	X-JUNCTION OF TUAS SOUTH AVE 3 / AVE 7
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC841J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TECH MARINE OFFSHORE (S) PTE LTD
Co Reg No	2XXXXX260M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68989181

### Vehicle Particulars

Manufacturer	SCANIA
Model	KIB4X2-8.9 ABS (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	GA413021
Cover Note Number	

### Driver

Name of Driver	GOVINDAN SIVAKUMAR
NRIC No	SXXXX932Z
Date Of Birth	18/06/1972
Occupation	OUTDOOR
Date Of Driving Pass	12/11/2007
Driving Experience	12 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85552865
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address BLK 93 DAWSON ROAD #27-34

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

### General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION

Weather Conditions CLEAR

Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

### Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name 10 UBI AVENUE 3

Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

REFER SKETCH PLAN & POLICE REPORT NO. T/20201019/2076

### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YQ342C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage



of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

GOVINDAN SIVAKUMAR

Approximate Age

Injuries Sustain

Injured person in which vehicle?

YQ342C

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 16/10

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN

Refer attachment

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling in my vehicle A (PC841J) along  
Turas South Ave S. At the traffic light junction, I proceed  
to travel straight as the traffic light were green.

Few seconds later, I suddenly felt and heard a loud  
sound my vehicle A then steered to the right. I  
tried to gain control of my vehicle A, however my  
vehicle A went up the pavement.

I felt pain on my back hence I called my colleague  
about the accident. He then arrived at the accident  
scene to assist me out from the vehicle. I was  
then conveyed by the ambulance to the hospital.

vehicle B (Y0342C) told my colleague that he had  
fall asleep and hence did not realize that the  
traffic light were red.

I wish to inform that there was a surveillance camera  
near the junction. (camera detail: LP215A/C21)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 16/10


Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:

$$A = K_{SH, J}$$

3426

Date of Incident : 11 Oct 2020

Time of Accident: 1920 hrs







**SINGAPORE  
POLICE FORCE**



T/20201019/2076

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20201019/2076

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 19/10/2020 16:06		Vide Report No.: J/20201011/0207		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: GOVINDAN SIVAKUMAR			Address: APT BLK 93 DAWSON ROAD #27-34 SKYTERRACE @ DAWSON SINGAPORE 142093		
ID Type / ID No.: NRIC NO / S7264932Z			Contact No.: Home/Office: Mobile: 85552865		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 48	Date of Birth: 18/06/1972	Type of Informant: Driver		
Race:			Language:		Institution / School Name:
Occupation: OTHERS			Driving Licence Information: Class: 3,4 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 11/10/2020 19:15	Type of Location:
Location:  TUAS SOUTH AVENUE 3				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:			Anyone conveyed by ambulance: Yes	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PC841J	Bus/Coach/Mi nibus					0
YQ342C	Bus/Coach/Mi nibus					0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report Pg. 2



SINGAPORE  
POLICE FORCE



1/20201019/2076

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. 1/20201019/2076

CONTINUATION OF REPORT

Driver			
Name	GOVINDAN SIVAKUMAR	ID No.	S7264932Z
Related Vehicle	NIL	Contact No.	85552865
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	14	Degree of Injury	NIL

**Brief Details.**

ON THE ABOVE MENTIONED DATE AND TIME,

I WAS DRIVING ALONG THE JUNCTION OF TUAS SOUTH AVENUE 3 AND AT THE JUNCTION OF AVENUE 3 AND AVENUE 7. I CONTINUED TO GO STRAIGHT AS THE TRAFFIC LIGHTS WERE GREEN. A FEW SECONDS LATER I FELT A STRONG IMPACT AND SOUND, MY VEHICLE WAS STEERED TOWARDS THE RIGHT I TRIED TO REGAIN CONTROL, MY VEHICLE ENDED UP MOUNTING THE KERB. I FELT SOME PAIN AND CALLED FOR MY COLLEAGUE TO DOWN. I WAS LATER CONVEYED TO THE HOSPITAL. I DID NOT MANAGE TO EXCHANGE PARTICULARS WITH THE OTHER DRIVER'S PARTICULARS. HOWEVER MY COLLEAGUE SHOULD HAVE DONE SO. THERE IS A SURVEILLANCE CAMERA(LP2151A/C21) AT THE TRAFFIC JUNCTION. THE OTHER DRIVER TOLD MY COLLEAGUE THAT HE HAD FALLEN ASLEEP AND DID NOT NOTICE THAT THE TRAFIC LIGHTS HAD TURNED RED.

IO IN CHARGE IS IO'FEROZ

# SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133  
T 65 6758 2222 F 65 6257 6931  
E sales@scauto.com.sg  
scauto.com.sg

Co. Reg. No. 199800107D

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

M/S TECH MARINE OFFSHORE (S) PTE LTD  
Acknowledged by Repairer  
Signature: 13 Tuas South Street 3  
Singapore 638019

Insured TECH MARINE OFFSHORE (S) PTE LTD  
Policy GA413021

Damaged Vehicle No: PC841J

## ESTIMATE Bill

GST Reg. No: 19-9800107D  
Date: 20/10/2020  
Our Case Ref. SC20/10/119/4TM-TP  
Accident Date 11/10/2020

S/no	Description	QTY	Price	Disc	Amount
<b>Replaced Parts</b>					
1	LHS SIDE VIEW MIRROR / CRU.	1	PC \$1,980.00		\$1,980.00
2	FRONT WINDSCREEN / BR	1	PC \$4,370.30		\$4,370.30
3	RUBBER GLASS / NEC	1	PC \$262.30		\$262.30
4	SEALANT / NEC	28	PC \$49.00		\$1,372.00
5	FRONT WIPER SET / CRU	1	PC \$1,980.00		\$1,980.00
6	FRONT CAP (1/2 SECTION) / BR	1	PC \$2,400.00		\$2,400.00
7	FRONT CAP STRUCTURE (1/2 SECTION) / BT.	1	PC \$2,500.00		\$2,500.00
8	FRONT SALOON / CRU	1	PC \$1,200.00		\$1,200.00
9	FRONT SALOON EXTENSION / BT	1	PC \$1,400.00		\$1,400.00
10	FRONT SALOON STRUCTURE FRAME	1	PC \$1,500.00		\$1,500.00
11	FRONT BUMPER / CRU.	1	PC \$1,800.00		\$1,800.00
12	FRONT BUMPER STRUCTURE / BT	1	PC \$1,920.00		\$1,920.00
13	LHS FOG LAMP COVER / CRU.	1	PC \$136.00		\$136.00
14	RHS FOG LAMP COVER / CRA	1	PC \$136.00		\$136.00
15	FOG LAMP LH / CRU	1	PC \$160.00		\$320.00
16	LHS HEADLAMP / CRU	1	PC \$1,196.00		\$1,196.00
17	FRONT NUMBER PLATE / PD	1	PC \$50.00		\$50.00
18	EMBLE 'SCANIA' / NEC	1	PC \$108.00		\$108.00
19	ARTWORK sticker / NEC	1	PC \$800.00		\$800.00
20	FRONT PASSENGER DOOR ASSEMBLY / CRU	1	PC \$3,150.00		\$3,150.00
21	FRONT DOOR ARM ASSEMBLY / BT	1	PC \$550.00		\$550.00
22	RUBBER DOOR GASKET / NEC	2	PC \$140.00		\$280.00





# SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222

F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S TECH MARINE OFFSHORE (S) PTE LTD

13 Tuas South Street 3  
Singapore 638019

Insured TECH MARINE OFFSHORE (S) PTE LTD

Policy GA413021

Damaged Vehicle No: PC841J

## ESTIMATE Bill

GST Reg. No: 19-9800107D

Date: 20/10/2020

Our Case Ref. SC20/10/119/4TM-TP

Accident Date 11/10/2020

S/no	Description	QTY	Price	Disc	Amount
23	FRONT PASSENGER DOOR ALUMINIUM PROFILE / NT	1 PC	\$240.00		\$240.00
24	FRONT PASSENGER GLASS DOOR / BK	1 PC	\$448.00		\$448.00
25	STAIRS ASSEMBLY ?	1 PC	\$2,800.00		\$2,800.00
26	STAIRS HANDLE BAR / BT	1 PC	\$280.00		\$280.00
27	STANCHION POLE ?	1 PC	\$580.00		\$580.00
28	FRONT DOOR TOP GLASS / BK	1 PC	\$325.00		\$325.00
29	SIDE DECORATION PANEL / SCR	1 PC	\$300.00		\$300.00
30	FRONT LHS MUDGUARD PANEL X R	1 PC	\$1,056.00		\$1,056.00
31	RHS STABILIZER BAR ?	1 PC	\$127.00		\$127.00
32	RHS TORSION BAR ?	1 PC	\$395.00		\$395.00
33	FRONT RHS MUDGUARD ?	1 PC	\$520.00		\$520.00

### Labour Charges

1	LABOUR FOR SPRAY PAINTING	1	\$3,500.00	-	\$3,500.00
2	LABOUR FOR WIRING	1	\$1,280.00	-	\$1,280.00
3	LABOUR FOR GLASS 4 glass	1	\$1,550.00	-	\$1,550.00
4	LABOUR FOR UNDERCARRIAGE & MECHANICAL	1	\$2,560.00	-	\$2,560.00
5	LABOUR FOR UPHOLSTERY & MATERIAL	1	\$1,920.00	-	\$1,920.00
6	LABOUR FOR FRONT & RHS PORTION 4	1	\$7,680.00	-	\$7,680.00

\$840 - days

Repair day - 10  
17 days

\* Labour to be confirm

2,000

3,000

200

1,280

1,280

1,280

1,280

1,280

1,280

1,280

1,280

Sub Total

\$54,971.60

Authorised Signature

TP with prejudice

8661 2627

Sunpin @11K auto.com



Connect with Facebook

HOMENEW CARSEUSED CARSCOMMERCIAL VEHRENTAL CARSELL CARSMOTOR DIRECTORYARTICLES





Home > Used Commercial Veh > Scania KIB4X2

DIRECT SELLER

SCANIA KIB4X2

OVERVIEWGALLERY

Share



Price

\$115,000

Registration Date

07-Dec-2011

COE Remaining

1yr 1mth 8days

Manufactured

2011

Mileage

402,000 km

No. of Owners

3

Transmission

Manual

Engine Capacity

11,705 cc

Fuel Type

Diesel

COE

\$40,189

Paper Value

\$4,448


Depreciation

\$103,900 / year

Type

Bus/Mini Bus

to covered



USED VEHICLE SEARCH

scania

CategoryVehicle Type

TransmissionEngine Capacity

Min PriceMax Price

Min DepreciationMax Depreciation

From Reg YearTo Reg Year

Good In Condition And Low Price. PM If Interested To Arrange For Bus Viewing. Price Negotiable.

Features: 49 Seater.


For full set of payment break-down, <https://www.sgcarmart...=914903&DL=1000>


Status: Available | Category: Direct Seller Vehicles, Diesel Vehicles


Date Posted: 26-Oct-2020 | Date Updated: 26-Oct-2020

SELLER INFORMATION


DIRECT SELLER

Ms Ling

62612278

EMAIL SELLER

"SAY YOU SAW THIS AD ON STCARS.SG!"



Instructions


on how to complete a seller to end-consumer deal

Once buyer & seller confirms the deal, sgCarMart Connect will provide 100% FREE settlement on Loans, Insurance & Paperwork for both parties. Call 6744 3540.

These are the essential forms to facilitate direct buyer and seller exchanges.

Indemnity Form | Sales Agreement | LTA Vehicle Transfer Form | Handover Form | Invoice

SIMILAR VEHICLES




Mercedes-Benz V-Class

V220 CDI Extra-Long

19-Oct-2018


\$112,000

Tags: Scania KIB4X2 Car, 2011 Scania KIB4X2 Car, KIB4X2 Car, Used Scania Car, Used Scania KIB4X2 Photos




ADVICE

Road tax renewal: Everything you need to know




FEATURE

Beyond the price tag - four more things to consider when buying a new car



ADVICE

COE renewal: What costs can you expect?



SELL CAR

Get over 500 dealers to compete for your car

New Cars

BMW cars

Audi cars

Volkswagen cars

Mercedes Benz Cars

Hyundai Cars

Toyota Cars

Honda Cars

Used Cars

Toyota Cars

Honda Cars

BMW Cars

Hyundai Cars

Nissan Cars

Mercedes Benz Cars

Car Rental and Leasing

Passenger Car Rental

Passenger Car Leasing

Car Sharing

Commercial Vehicle Leasing

Chauffeur & Limousine Service

Wedding Car Rental

Motoring Directory

Servicing and Repair

Car Grooming

Car Audio and Entertainment

Tyres Rims and Batteries

Spray Painting and Body Repair

Car Insurance Singapore

Articles

Car Reviews

Motoring News

Motoring Guides

COE

Car Park Rates

Sell Cars

Car Forum

Car Club

Motor Insurance

Car Discussion

Forum Discussion

Car Accessories

Car Blog

Affiliate Site

Singapore Cars

Car Rental


Car Workshop

Car Reviews

Used Car Dealers

New Car Dealers

Affiliates:



About Us | Contact Us | Advertise With Us | Terms & Conditions | Privacy Policy | Personal Data Protection Statement | Site Map

https://www.stcars.sg/singapore-car/commercial-vehicles/scania-kib4x2-a914903/overview

1/1