

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |   |   |                                |            |  |
|---|---|---|--------------------------------|------------|--|
| UNITED OVERSEAS INSURANCE LTD                                     |   |   | Ref : CS/UOI20011606/Uqf3e2    |            |  |
| 3 ANSON ROAD #28-01<br>SPRINGLEAF TOWER SINGAPORE 079909          |   |   | Date: 20-11-2020<br>Code: UOI2 |            |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM                        |   |   |                                |            |  |
|   | Insured Veh.  | SMJ 2483U   | Veh. Inspected                 | FBM 5666D  |  |
|   | Policy No.  |   | Coverage (\$)                  | 0.00       |  |
|   | Claim No.   | M12D14122011  | Excess (\$)                    | 0.00       |  |
|   | Assign From   | JOSEPHINE WONG                                      | Assign Date                    | 26/10/2020 |  |
| 2. Vehicle Particulars & Condition                                |   |   |                                |            |  |
|   | Make & Model  | HONDA CB150R  | c.c                            | 149        |  |
|   | Engine No.  | HIDDEN  | Year of Reg.                   | 2017       |  |
|   | Chassis No.   | MLHKC2886J5005923                                   | Colour                         | RED        |  |
|   | Odometer  | 54057   | Steering                       | AFFECTED   |  |
|   | Brakes  | IN ORDER  | Modification                   | SPORTS RIM |  |
|   | General   | GOOD  |                                |            |  |
| 3.  | 3. Conditions of Tyres  |   |                                |            |  |
|   |   | Size  | Make                           | Balance    |  |
|   | R/H Front Tyre  | 110/70 R17  | PIRELLI                        | 7 mm       |  |
|   | L/H Front Tyre  |   |                                | mm         |  |
|   | R/H Rear Tyre   | 150/60 R17  | PIRELLI                        | 7 mm       |  |
|   | L/H Rear Tyre   |   |                                | mm         |  |
| 4.  | Description of Damages  |   |                                |            |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND N/S FRONT PORTION.  |   |                                |            |  |
|   | DAMAGES SEE DETAILS.  |   |                                |            |  |
| 5.  | General Information   |   |                                |            |  |
|   | Accident Date   | 16/10/2020  | Inspection Date                | 28/10/2020 |  |
|   | Survey held at EROFIA MOTOR TRADING PTE LTD   |   |                                |            |  |
|   |   | 1 KAKI BUKIT AVENUE 6<br>#02-62<br>SINGAPORE 417883 |                                |            |  |
| 5a.   | Remarks   |   |                                |            |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                                |            |  |
| 5b.   | D)IN ACCORDANC  | Estimate Days of Repair                             |                                |            |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days  |   |                                |            |  |
|   |   |   |                                |            |  |