







NTU	NTUC INCOME INSURANCE CO-OPERATIVE LTD			NS/INC20011607/Etd3e2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	02-11-2020 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLH 609K	Veh. Ir	nspected	SHB 3111M	
	Policy No.	5119105131	Cover	age (\$)	0.00	
	Claim No.	MT/1107915-002	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	26/10/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2019	
	Chassis No.	KMHC851CVKU164822	Colou	r	BLUE	
	Odometer	99757	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	FIREST	TONE	4 mm	
	L/H Front Tyre	195/65 R15	FIREST	TONE	4 mm	
	R/H Rear Tyre	195/65 R15	FIREST		4 mm	
	L/H Rear Tyre	195/65 R15	FIREST	TONE	4 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	24/10/2020	Insped	tion Date	26/10/2020	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD  59 LOYANG DRIVE SINGAPORE 508969					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:		2 Working Days		