

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC20011614/Etd3q2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	04-11-2020 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	FBG 677L	Veh. Ir	spected	SHC 2461D	
	Policy No.	5117022666	Cover	age (\$)	0.00	
	Claim No.	MT/1107555-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	26/10/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2018	
	Chassis No.	KMHC851CVKU122083	Coloui	r	BLUE	
	Odometer	255399	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	GOOD	/EAR	5 mm	
	L/H Front Tyre	195/65 R15	GOOD\	/EAR	5 mm	
	R/H Rear Tyre	195/65 R15	GOOD'	/EAR	5 mm	
	L/H Rear Tyre	195/65 R15	GOOD'	/EAR	5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	21/10/2020	Inspec	tion Date	26/10/2020	
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					

Estimate Days of Repair

2 Working Days