

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 26.10.2020
Time: 15:02:00
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305429978
REGN NO : SHD4800R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 24.07.2019
DATE/TIME IN : 26.10.2020 11:00
ACCIDENT DATE : 23.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-1150-A IONIQVC PROTECTOR MAT , 1 N 50.00 0.00 50.00 X NM

0002 04-01-0101-0111-G HYUNDAI BUMPER COVER CLIP 10 L 22.00 20.00 17.60 X NM

SUB-TOTAL : 67.60

JOB NATURE

0000 L PANEL BEATING

350.00 320

0001 23-502 SPRAYPAINT ON AFFECTED AREA

250.00 200

SUB-TOTAL : 600.00

TOTAL : 667.60

AUTHORISED : YES / NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE :

DATE :

Sten (CLKK) Mr
26/10/20, 4.00 pm

2 dys

P/P

Ry Bel Smy

- Link Auto Consultants hereby notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: