

Our Job Ref No 305429978Date : 02.11.20ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : Mr STEVEVehicle Reg No. SHD4800R CTPL23.10.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FBD7564Z


2. The finalized amount shall be:

(a) Spare Parts after List discount \$0.00(b) Labour Charges \$520.00**Total for Part-By-Part Repair Cost** \$520.00

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%**Final Lumpsum Repair cost**3. Estimated normal period for repairs: 2 working days.4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : Name : LIM KWOK ENGTel : 62148316Fax : 65468156Signature : Name : SteveDate : 3/11/20**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305429978
REGN NO : SHD4800R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 24.07.2019
DATE/TIME IN : 26.10.2020 11:00
ACCIDENT DATE : 23.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-1150-A IONIQVC PROTECTOR MAT 1 N 50.00 0.00 50.00 X

0002 04-01-0101-0111-G HYUNDAI BUMPER COVER CLIP 10 L 22.00 20.00 17.60 X

SUB-TOTAL : 67.60

JOB NATURE

0000 L PANEL BEATING

350.00

320

0001 23-502 SPRAYPAINT ON AFFECTED AREA

250.00

200

SUB-TOTAL : 600.00

TOTAL : 667.60

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Stew (CLKK) Mr Pm
26/10/20, 4.00 pm
2 dys
P/P
By Bel Smy

COMFORTDELGRO ENGINEERING PTE LTD

Date: 02.11.2020

REPAIR ESTIMATE

Time: 10:10:23

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305429978
REGN NO : SHD4800R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 24.07.2019
DATE/TIME IN : 26.10.2020 11:00
ACCIDENT DATE : 23.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0000 L PANEL BEATING 320.00

0001 23-502 SPRAYPAINT ON AFFECTED AREA 200.00

SUB-TOTAL : 520.00

TOTAL : 520.00

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO