

Our Job Ref No 305430193

Date : 02.11.20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr STEVE

Vehicle Reg No. SHA7327L CTPL

21.10.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FBD7564Z
2. The finalized amount shall be:

(a) Spare Parts after List discount	<u>\$1,851.26</u>
(b) Labour Charges	<u>\$1,390.00</u>
Total for Part-By-Part Repair Cost	<u>\$3,241.26</u>
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	<u> </u>
Final Lumpsum Repair cost	<u> </u>

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : Steve

Date : 3/11/20

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305430193
 REGN NO : SHA7327L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 16.01.2020
 DATE/TIME IN : 26.10.2020 09:20
 ACCIDENT DATE : 21.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0594-G	IONIQV1 MIRROR ASSY-OUTSI	1 L	1,054.60	20.00	843.68	X	check (No damaged) N/A
0002 04-01-0104-0592-G	IONIQVC PANEL ASSY-FRONT	1 L	1,797.20	20.00	1,437.76	/	00
0003 04-01-0104-2468-G	IONIQVC MOULDING ASSY-W/L	1 L	116.20	20.00	92.96	/	CUT
0004 04-01-0104-2470-G	IONIQVC MOULDING ASSY-W/L	1 L	116.20	20.00	92.96	/	CUT
0005 04-01-0104-0810-G	IONIQVC MOULDING ASSY-SID	1 L	290.00	20.00	232.00	X	R (Rocker part growth)
0006 28-01-0103-0003-A	(I40)FRT DOOR LOGO CTPL	1 N	75.00	10.00	67.50	/	pre
0007 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	10.00	72.00	/	pre
(Supp) - Frt Door Outer Moulding Rh - \$110.10						/	00
						SUB-TOTAL : 2,838.86	

JOB NATURE

0000 L	PANEL BEATING (frt WS pillar Rh)	700.00	480
0001 23-502	SPRAYPAINT ON AFFECTED AREA	850.00	800
0002 17-01	CHECK ALL LIGHTING	50.00	30
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30

Stew (LKK) wL PL
 26/10/20, 4.30pm
 3 days
 P/P
 My Bel Sky

COMFORTDELGRO ENGINEERING PTE LTD

Date: 26.10.2020

REPAIR ESTIMATE

Time: 16:26:45

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305430193
REGN NO : SHA7327L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 16.01.2020
DATE/TIME IN : 26.10.2020 09:2
ACCIDENT DATE : 21.10.2020

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0004 20-02 TRANSFER OF DOOR	120.00		50		

SUB-TOTAL : 1,770.00

TOTAL : 4,608.86

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :
AUTHORISED : YES / NO

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 30.10.2020

Time: 18:24:21

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305430193
REGN NO : SHA7327L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 16.01.2020
DATE/TIME IN : 26.10.2020 09:20
ACCIDENT DATE : 21.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0592-G	IONIQVC PANEL ASSY-FRONT	1 L	1,797.20	20.00	1,437.76
0002 04-01-0104-2468-G	IONIQVC MOULDING ASSY-W/L	1 L	116.20	20.00	92.96
0003 04-01-0104-2470-G	IONIQVC MOULDING ASSY-W/L	1 L	116.20	20.00	92.96
0004 04-01-0104-2600-G	IONIQV2&3 W/STRIP ASSY-FR	1 L	110.10	20.00	88.08
0005 28-01-0103-0003-A	(I40)FRT DOOR LOGO CTPL	1 N	75.00	10.00	67.50
0006 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	10.00	72.00

SUB-TOTAL : 1,851.26

JOB NATURE

0000 L	PANEL BEATING (frt WS pillar Rh)	480.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	800.00
0002 17-01	CHECK ALL LIGHTING	30.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	30.00
0004 20-02	TRANSFER OF DOOR	50.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305430193
REGN NO : SHA7327L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 16.01.2020
DATE/TIME IN : 26.10.2020 09:2
ACCIDENT DATE : 21.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 1,390.00

TOTAL : 3,241.26

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :