

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 26.10.2020
Time: 16:26:45
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305430193
REGN NO : SHA7327L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 16.01.2020
DATE/TIME IN : 26.10.2020 09:20
ACCIDENT DATE : 21.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0594-G	IONIQV1 MIRROR ASSY-OUTSI	1 L	1,054.60	20.00	843.68	X	(No damaged) N/A
0002 04-01-0104-0592-G	IONIQVC PANEL ASSY-FRONT	1 L	1,797.20	20.00	1,437.76	✓	00
0003 04-01-0104-2468-G	IONIQVC MOULDING ASSY-W/L	1 L	116.20	20.00	92.96	✓	CUT
0004 04-01-0104-2470-G	IONIQVC MOULDING ASSY-W/L	1 L	116.20	20.00	92.96	✓	CUT
0005 04-01-0104-0810-G	IONIQVC MOULDING ASSY-SID	1 L	290.00	20.00	232.00	X	R (Rocker panel scratch)
0006 28-01-0103-0003-A	(I40)FRT DOOR LOGO CTPL	1 N	75.00	10.00	67.50	✓	PL
0007 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	10.00	72.00	✓	PL
						✓	00
						SUB-TOTAL : 2,838.86	

JOB NATURE

0000 L	PANEL BEATING (frt WS pillar Rh)	700.00	480
0001 23-502	SPRAYPAINT ON AFFECTED AREA	850.00	800
0002 17-01	CHECK ALL LIGHTING	50.00	30
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30

Stew (LKK) w/L PL
26/10/20, 4.30pm
3 dys
P/P
My Bel Sky

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 26.10.2020
Time: 16:26:45
Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305430193
REGN NO : SHA7327L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 16.01.2020
DATE/TIME IN : 26.10.2020 09:2
ACCIDENT DATE : 21.10.2020

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0004 20-02 TRANSFER OF DOOR	120.00		50		
SUB-TOTAL :					1,770.00

TOTAL : 4,608.86

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: