

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 26.10.2020
Time: 12:29:40
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305429975
REGN NO : SHA4368M
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 27.02.2019
DATE/TIME IN : 26.10.2020 08:50
ACCIDENT DATE : 21.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 03-01-0104-2137-G IONIQV4 CAP ASSY-WHEEL HU 1 L 346.40 20.00 277.12 ✓ DR
SUB-TOTAL : 277.12

JOB NATURE

0000 20-05 REAR FENDER ADVERTISMENT LOGO RH 100.00 ✓
0001 L PANEL BEATING (rear bumper & fender R 480.00 329
0002 23-502 SPRAYPAINT ON AFFECTED AREA 450.00 400
0003 20-08 ADJUST REAR WHEEL ALIGNMENT 80.00 60
SUB-TOTAL : 1,110.00 = 1157.12
TOTAL : 1,387.12 ✓

MVA NAME & SIGNATURE
DATE :

Steve (LKK)

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

W ML
26/10/20, 3.00pm

2 dy,
P/P

My Ben Ly

KK Auto Consultants hence notify
the Repairer of the following:
To resurvey before/after spray painting
To display damaged part(s) during resurvey
Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

acknowledged by Repairer

Signature:

Date: