

Your Ref: RT/SB/166/2020/XF

Date: 21st Jan 2021

Our Ref: CS1/LAW20011657/Avf3e2

M/s Tan Chin Hoe & Co

24 Raffles Place

#24-01 Clifford Centre

Singapore 048621

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJR 7374L
INSURED VEHICLE: SKL 2385H
ACCIDENT DATE: 29/01/2020**

We thank you for your instruction on 26/10/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJR 7374L from M/s Pal's Appraiser Pte Ltd.
- b) Survey report by L.B.S. Auto Consultants Pte Ltd with colour photographs.
- c) Final Repair Bill of SJR 7374L from M/s Hua Meng Spray Painting Workshop.
- d) Singapore Accident Statement of Vehicles SJR 7374L and SKL 2385H.
- e) Colour damaged vehicle photographs of SJR 7374L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJR 7374L
Make & Model	: Hyundai HD Avante 1.6A
Chassis Number	: KMHDU41BR9U774252
Year of Registration	: 2009
Engine Capacity	: 1591 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.