

Surveyor:

REF: CSI / LAW20011657 / Ayf3

Special Instruction:

Part By Part: 4402.16

Third Parties:

Claimant:

Surveyor:

Workshop: Hua mng spray

From (Person): Elaim Toh of LAW Date/Time: 26-10-2020  
Estimated Cost: Bill to:

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SJR 7374 L

Insured: SKL 23854

at Workshop m/s Hua mng spray

Tel: 67478064 / 67465519

of 1 KAK BUKIT

RT/SB/166/2020/XF

Policy No: RT/SB/166/2020/XF

Claim No: RT/SB/166/2020/XF

Sum Insured:

Excess:

Make of Veh:

D.O.A. 29.01.2020

(Client's Record)

SJE

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 4 days)

Date/Time: 21/1/21 Submit Final Fig LS \$3800, 5 days (Red \$602.16 / 14 %; Original days)

| Date/Time | Action/Instruction                                                       |
|-----------|--------------------------------------------------------------------------|
|           | <u>SJR 7374 L - X</u>                                                    |
|           | <u>SKL 23854 - X</u>                                                     |
|           | <u>Bill Tan Chin Hoe 50% / Vision LAW 50% (confirm with Richard Tan)</u> |
|           | <u>Received Richard Tan email on 27/10/2020 6:11p.m.</u>                 |
|           |                                                                          |
|           |                                                                          |
|           |                                                                          |
|           |                                                                          |
|           |                                                                          |
|           |                                                                          |
|           |                                                                          |

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/  
Evaluated by:

Fee Charged:

Basic & Add  
Transport  
Photos  
Others  
Total

Date:

|  |
|--|
|  |
|  |
|  |
|  |
|  |

- |              |              |              |                |
|--------------|--------------|--------------|----------------|
| 1) Date/Time | File Pass to | 2) Date/Time | File Return to |
| 3) Date/Time | File Pass to | 4) Date/Time | File Return to |
| 5) Date/Time | File Pass to | 6) Date/Time | File Return to |