

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
AUTO & GENERAL INSURANCE (S) PL			Ref : CS3/AGI20005995/Evf3e2-1		
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date: 04-11-2020		
			Code: AGI		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJF 1476D	Veh. Inspected	SDZ 848L	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10006294	Excess (\$)	0.00	
	Assign From	STANLEY LAI	Assign Date	27/10/2020	
2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. X6	c.c	2979	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	WBAFG42030LJ78376	Colour	WHITE	
	Odometer	94350	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	295/30Z R22	CONTINENTAL	5 mm	
	L/H Front Tyre	295/30Z R22	CONTINENTAL	5 mm	
	R/H Rear Tyre	295/30Z R22	CONTINENTAL	5 mm	
	L/H Rear Tyre	295/30Z R22	CONTINENTAL	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	11/05/2020	Inspection Date	28/05/2020	
	Survey held at	AUTOMEDIC HOLDING			
		BLK 25 SYNERGY @KB #05 - 85 KAKI BUKIT ROAD 4 SINGAPORE 417800			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: