

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
AUT	O & GENERAL IN	SURANCE (S) PL	Ref:	: CS/AGI20011694/Uvf3q2		
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date :			
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SGR 8527S	Veh. In	spected	FBL 2938U	
	Policy No.		Covera	ige (\$)	0.00	
	Claim No.	C10007727	Excess	5 (\$)	0.00	
	Assign From	IVY RATILLA	Assign	Date	27/10/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA 400X	c.c		399	
	Engine No.	HIDDEN	Year of	Reg.	2016	
	Chassis No.	NC471100718	Colour		WHITE	
	Odometer	74231	Steerin	g	IN ORDER	
	Brakes	IN ORDER	Modific	ation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	120/70Z R17	MICHEL	IN	6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	160/60Z R17	MICHEL	IN	6 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S & O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	25/10/2020	Inspect	tion Date	28/10/2020	
	Survey held at	TAN LIM MOTOR PTE LTD				
		NO.1 DEFU LANE 6 SINGAPORE 539365				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
1	1				· · · · · · · · · · · · · · · · · · ·	

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: