



PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD		Ref: CS3/LPC20011728/Qtd3e2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date: 09-11-2020		
		Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YM 9424L	Veh. Inspected	SGR 8271D
	Policy No.		Coverage (\$)	0.00
	Claim No.	20/20/20/VC00/023822	Excess (\$)	0.00
	Assign From	ONG LI LI	Assign Date	28/10/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA WISH 1.8X	c.c	1794
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	ZNE100354017	Colour	BLACK
	Odometer	387616 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	6 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	6 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
	L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.			
5. General Information				
	Accident Date	26/10/2020	Inspect Date / Time	28/10/2020 (04:50 PM)
	Survey held at	1 BUKIT BATOK CRESCENT #04-40		
	Repairer	JCM RENTAL PTE LTD		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC20011728/Qtd3e2

Inspected By



OI SUN PIN

Asst. Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.