



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI20011748/Aqf3n2 Date: 06/04/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGK 3252D	Veh. Inspected	GBC 8724C
Policy No.		Coverage (\$)	0.00
Claim No.	C10007755/LA	Excess (\$)	0.00
Assign From	ABIGAIL CHOO	Assign Date	28/10/2020
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NV200	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VSKYBAM20U0071848	Colour	SILVER
Odometer	121949 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/70 R14C	KENDA	6 mm
L/H Front Tyre	175/70 R14C	KENDA	6 mm
R/H Rear Tyre	175/70 R14C	KENDA	6 mm
L/H Rear Tyre	175/70 R14C	KENDA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	24/10/2020	Inspection Date	29/10/2020
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	