



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Ref: CS/UOI20011776/Bcf3e2	
			Date: 26/07/2021	
			Code: UOI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	WB 9360T	Veh. Inspected	SLJ 3915X
	Policy No.		Coverage (\$)	0.00
	Claim No.	M11D11132011	Excess (\$)	0.00
	Assign From	JOSEPHINE WONG	Assign Date	27/10/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA VEZEL	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	RU11104119	Colour	BLACK
	Odometer	149247 KM	Steering	JAMMED
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	POOR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	CHAMPIRO	7 mm
	L/H Front Tyre	215/60 R16	CHAMPIRO	7 mm
	R/H Rear Tyre	215/60 R16	CHAMPIRO	7 mm
	L/H Rear Tyre	215/60 R16	CHAMPIRO	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	24/10/2020	Inspection Date	27/10/2020
	Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	