

ASS. REC. BY:

REF:

AIG/200118181kb

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/LWS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1.B.1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/HB 96217

Yr Regn:

06, 1P

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Pous

c.c

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

176942

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU003081403

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

Sailun

195/65R15

R:

Pirelli

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

26/10/20

D.O.I.

28/10/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 177

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

B 912.00

Date/Time, File Pass to?

☐

Prell. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9621T**AAD2010-120***Not Authored**Resurvey B4 paint**\$912.00*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

20 OCT 2020**SHB9621T**

JTDKB3FU003081403

TOYOTA

PRIUS

26/10/2020

AIG

18/06/2019

PART

- 1 COVER, FRONT BUMPER
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 REINFORCEMENT, FRONT BUMPER, NO.2
- 1 FRONT BUMPER SIDE RETAINER RH
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 EXTENSION, FRONT BUMPER, RH
- 1 BRACKET, HEADLAMP, RH
- 1 UNIT ASSY, HEADLAMP, RH
- 1 LAMP ASSY, FOG, RH
- 1 LINER, FRONT FENDER, RH
- 1 FENDER SUB-ASSY, FRONT RH

	LIST		
\$	<i>Br/In</i>	516.00	✓
\$	<i>n</i>	716.60	
\$	<i>n</i>	246.10	
\$	<i>Sn</i>	80.10	} X
\$	<i>Sn</i>	59.30	
\$	<i>Sn</i>	80.10	
\$	<i>Sn</i>	120.10	
\$	<i>Sn</i>	34.80	
\$	<i>Sn</i>	2,637.60	X
\$	<i>n</i>	951.40	X
\$	<i>Sn</i>	206.70	X
\$	<i>n</i>	977.80	X
TOTAL	\$	6,626.60	
25%	\$	2,828.00	
	\$	8,484.00	

Special Nett

- 1 FRONT FENDER EMBLEM LH
- 1 WHEEL RIM COVER
- 1 TYRE 195/65/15
- 1SET FRONT FENDER LINER CLIP
- 1SET FRONT BUMPER CLIP

\$	<i>nn</i>	150.00	X
\$	<i>Sn</i>	211.50	X
\$	<i>Sn</i>	350.00	X
\$	<i>nn</i>	75.00	X
\$	<i>nn</i>	90.00	✓
TOTAL	\$	876.50	

TOTAL PARTS \$ 9,530.50**LABOUR**

Trans-cab Auto Services Pte Ltd**AAD2010-120**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9621T

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	1,600.00	2001
	\$	380.00	
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn 240.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	2201
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	151

TOTAL \$ 4,380.00**Over All Total \$ 13,740.50****(PART-BY-PART) Repair Days****10 days****2 day****For Official Use**Prepared By : _____
(Accident Dept)Verify By : _____
(Accident Workshop)

Checked By : _____

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: