

Our Job Ref No : 305431070Date : 02/11/20ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : STEVEVehicle Reg No. : SHC1580A30/10/2020


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- Z The repair job shall bill to: NTUC PA5852E
2. The finalized amount shall be:
- | | |
|---|-------------------|
| (a) Spare Parts after List discount | <u>\$80.00</u> |
| (b) Labour Charges | <u>\$920.00</u> |
| Total for Part-By-Part Repair Cost | <u>\$1,000.00</u> |
| (c) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | |
| Final Lumpsum Repair cost | |

3. Estimated normal period for repairs:
- 2
- working days.

- 4.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : Name : CHIANGTel : 62148314Fax : 65468156Signature : Name : SteveDate : 3/11/20**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305431070
REGN NO : SHC1580A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 10.07.2019
DATE/TIME IN : 30.10.2020 10:10
ACCIDENT DATE : 30.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 28-01-9999-2023-A APP LOGO REAR DOOR L/R CT 1 80.00 0.00 80.00

SUB-TOTAL : 80.00

JOB NATURE

0000 PB PANEL BEATING 320.00

0001 SP SPRAYPAINT CHARGE 600.00

SUB-TOTAL : 920.00

TOTAL : 1,000.00

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :