

ASS. REC. BY:

Ster

REF:

NTUC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Cum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHK 1580A Yr Regn: 10/7/19

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /

Truck / Trailer or

Make: Hyundai 10019 c.c. 1580Colour: Blue A/C: Insured / Std / NI / NSp. Reading: 169216 T/Radio: Insured / Std / NI / N

Eng/No: _____

G/No: KMH C851 CVR4-164580

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 30/10/20 D.O.I. 30/10/20Survey held at Com M. d. M. g. m.

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear R.H.

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Date/Time, File, Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Pop. Form:

Dump Sum / L.E. / P.

COMFORTDELGRO PTE LTD

REPAIR ESTIMATE*

30/10/20

VEHICLE NO SHC1580A

MAKE :

CHIANG/ NTUC

MODEL IONIQ G

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER X R			\$459.40
1	REAR BUMPER BRACKET /RH X N/A			\$55.80
				\$515.20
				\$103.04
				\$412.16
				\$80.00
				\$80.00
				\$320.00
				\$700.00
				\$1,020.00
				\$1,512.16

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Sten (LKK)

WL Pm

30/10/20, 4.10pm

P/P

My AL Sy

2 djs

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609288

320 B Road Singapore 660649

24 Senoko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768733

Date/Time: 30.10.2020 15:59

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.: 305431070

STOMER
COMFORT TRANSPORTATION PTE LTD
/MS 7010045
STOMER NO. 383 SIN MING DRIVE
DRESS Singapore SINGAPORE 575717
65508755 (R) (O)
(P)

REGN NO. SHC1580A	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 30.10.2020 10:10
YR OF MANU. 10.07.2019	TARGET DATE
CHASSIS CODE KMH851CVKU164580	COMPLETION DATE/TIME:


COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 30.10.2020
NATURE: 3P 30.10.2020

S/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

:

..

e No.:

SHC1580A

CHIANG

Exit Pass

Vehicle No.:

SHC1580A

Service Advisor

Signature/Date

Name of Service Advisor

Date

to Service Reception upon collection

To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 30/10/2020 12:17
Date Of Accident 30/10/2020 07:25
Exact Location Of Accident WOODLANDS ST 41 OPPOSITE BLK 421A
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC1580A
Insured/Policyholder
Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
Co Reg No 1XXXXX821R
Email Address FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No
Alternative Phone No OFFICE-65508768

Vehicle Particulars

Manufacturer HYUNDAI
Model IONIQ
Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy YES
Policy Number D-18088936MFSH
Cover Note Number

Driver

Name of Driver THAM KONG WENG
NRIC No SXXXX593F
Date Of Birth 26/02/1964
Occupation OUTDOOR
Date Of Driving Pass 09/02/1984
Driving Experience 36 YEARS AND 8 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96230131
Fax Number
Contact Number
Email Address ACESANDYLUCKY@YAHOO.COM.SG

Address BLK 469A YISHUN ST 43 #08-05
 Postcode 761469
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PA5852E
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category BUS
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Nature Of Damage LEFT FRT
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

me
Approximate Age
Injuries Sustain
Injured person in which vehicle?
Were seat belts worn?
Was this injured conveyed to hospital by
ambulance?
Address
Postcode

THAM KONG WENG

56

BACK PAIN

SHC1580A

YES

NO

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared/disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time: 30.10.2020
10.15h

Reporting Centre Personnel's Signature
Name: Larry Ng
NRIC/Fin No.:

SKETCH PLAN

WOODYLANDS ST 41



BLC 421A

A - SHC 1580A

B - PASSS22

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

→ Statement attached →

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 109303821R

Policyholder's Signature
Date & Time:

Driver's Signature _____
(if driver is not the policyholder)
Date & Time: 2.0.10.20

Date & Time: 30.10.2020
10:50am

Reporting Centre Personnel's Signature
Name: Larry Ng
NRIC/Fin No:

Sketch Plan Pg. 3

Describe Circumstances of the Accident.

On 30.10.2020, at about 0725hrs, I was sending my female pax to the American School,

Woodlands St 41. Traffic was heavy. My pax decided to alight and walk to the school.

There were many vehicles in front of me. She alighted. The front traffic then started to

move. I moved too. Suddenly, a van, B, which was behind me, tried to overtake my taxi

and its left front side hit my taxi right rear side.

Photos taken after the accident showing B was over the center white line and was

overtaking against the flow of traffic.

After the accident, I feel pain in my back.

Declaration

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303921R

Policyholder's Signature/Date &
Time

Driver's Signature (If driver is not the policyholder)/Date
& Time

Tham
30-10-2020
10.15h

Larry Ng
Witnessed by Reporting
Centre Personnel

