



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI20011886/Gcd3n2	Date: 07/06/2021
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDV 1827L	Veh. Inspected	SFB 3373Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10007779/KY	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	30/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SUNNY 1.6	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JN1CFAN16Z0131341	Colour	BEIGE	
Odometer	184592 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	FALKEN	6 mm	
L/H Front Tyre	185/65 R15	FALKEN	6 mm	
R/H Rear Tyre	185/65 R15	FALKEN	6 mm	
L/H Rear Tyre	185/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/10/2020	Inspection Date	30/10/2020	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	